



report date: 2024-03-28

General information

Make	VOLVO
Model	S80 D5 SE
Colour	Silver
Year of manufacture	2009
Top speed	140 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	180 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-01-19
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-11-17
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	38
Total items failed	12

MOT #17	2022-11-15 10:59
MOT test number	456461597232
Result	✓ Passed
Next expiry date	2023-11-17
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #16	2021-11-18 17:50
MOT test number	459962206766
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Tyre size: 225/50R17 (5.2.3 (d) (ii))

MOT #15	2020-11-12 15:04
MOT test number	201452242471
Result	✓ Passed

MOT #14	2020-11-12 15:04
MOT test number	524743514128
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #13** 2019-04-18 16:12**MOT test number** 132881932557**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2019-04-18 11:28**MOT test number** 815890808377**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Front Windscreen washer not working (3.5 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2018-07-18 13:12**MOT test number** 899032469523**Result** ✓ Passed**MOT #10** 2017-10-23 14:15**MOT test number** 302732501553**Result** ✓ Passed**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Advice** EML light is on

**MOT #9**

2017-10-23 14:15

MOT test number

629587902756

Result**✗ Failed****Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** EML light is on**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #8**

2016-10-21 07:03

MOT test number

936691474047

Result**✓ Passed****Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7**

2016-10-18 08:39

MOT test number

563593595714

Result**✗ Failed****Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** EML light is on**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #6 2015-10-10 09:58

MOT test number 861167372649

Result ✓ Passed

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Advice CAM BELT RENEWAL CHECK SESCICE INTERVAL

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #5 2015-10-10 09:58

MOT test number 177415733831

Result ✗ Failed

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Pass with rectification Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice CAM BELT RENEWAL CHECK SESCICE INTERVAL

Pass with rectification Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #4** 2014-11-04 09:17**MOT test number** 969028404349**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Front brake discs are lipped and worn**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Check brake pads in 4 - 6 months**MOT #3** 2014-11-04 09:17**MOT test number** 486998704326**Result** ✗ Failed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Front brake discs are lipped and worn**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Check brake pads in 4 - 6 months**Pass with rectification** Offside Front Headlamp aim too low (1.8)**MOT #2** 2013-09-30 11:23**MOT test number** 607553973229**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1	2012-09-05 16:56
MOT test number	935519442200
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

X

Untaxed

Tax expired:
31 July 2023

X

MOT

Expired:
17 November 2023

Tax status	Expired at 31 July 2023
Days left	273 days too late
MOT expiry date	17 November 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KA03HAO
Plate since	2019-03-28
Current registration	KA03HAO
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-29
Last registration	2022-11-15
Complete history	See info



Registration #1	2009-09-29	23 mi
Registration #2	2012-09-05	52.748 mi
Registration #3	2013-09-30	64.890 mi
Registration #4	2014-11-04	76.752 mi
Registration #5	2015-10-10	90.671 mi
Registration #6	2015-10-10	90.671 mi
Registration #7	2016-10-18	103.992 mi
Registration #8	2016-10-21	103.992 mi
Registration #9	2017-10-23	123.671 mi
Registration #10	2019-05-29	151.377 mi
Registration #11	2019-05-29	151.377 mi
Registration #12	2019-05-29	151.377 mi
Registration #13	2019-05-29	151.377 mi
Registration #14	2019-05-29	151.377 mi
Registration #15	2019-05-29	151.377 mi
Registration #16	2019-05-29	151.377 mi
Registration #17	2019-05-29	151.377 mi
Registration #18	2019-05-29	151.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1847 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1773 kg
Max. allowed weight	2130 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number

764294