



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MASTER MM33 MWB L/C P/V 100
Colour	Grey
Year of manufacture	2008
Top speed	86 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	260 Nm at 1.600 rpm
Engine capacity	2.464 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	36.2 mpg
Consumption combined	32.1 mpg





MOT history

MOT expiry date	2023-09-22
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	34
Total items failed	5

MOT #19	2022-09-23 10:27
MOT test number	179565810011
Result	✓ Passed
Next expiry date	2023-09-22
Advice	N/s park brake requires attention.

MOT #18	2022-09-23 10:27
MOT test number	461901781740
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	N/s park brake requires attention.

MOT #17	2021-09-07 13:01
MOT test number	337726208004
Result	✓ Passed

MOT #16	2021-09-07 13:01
MOT test number	404913078004
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))



MOT #15	2020-02-27 16:55
MOT test number	755514806722
Result	✓ Passed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #14	2020-02-20 10:49
MOT test number	217309342841
Result	✗ Failed
MAJOR	Rear Service brake imbalanced across an axle (1.2.1 (b) (i))
MAJOR	Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
DANGEROUS	Nearside Rear Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
DANGEROUS	Rear Leaf spring main leaf fractured both sides (5.3.1 (b) (ii))
MAJOR	Horn not working (7.7 (a) (ii))
DANGEROUS	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
MAJOR	Rear Anti-roll bar pin or bush excessively worn d bushes (5.3.4 (a) (i))

MOT #13	2019-03-07 16:31
MOT test number	906228024111
Result	✓ Passed
Advice	Rear suspension slightly low
Advice	Exhaust slightly corroded
Advice	Offside Front Steering linkage ball joint has slight play (2.1.3 (b) (i))

**MOT #12**

2019-03-07 11:25

MOT test number

503090037652

Result**✗ Failed****Advice** Rear suspension slightly low**MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Exhaust slightly corroded**Advice** Offside Front Steering linkage ball joint has slight play (2.1.3 (b) (i))**MAJOR** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))**MOT #11**

2018-03-09 09:50

MOT test number

418674629625

Result**✓ Passed****Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #10**

2017-02-17 09:37

MOT test number

768210912198

Result**✓ Passed****Advice** Offside Front Lower Suspension arm has slight play in a ball joint ball joint has lift (2.4.G.2)**MOT #9**

2017-02-16 17:34

MOT test number

586825548849

Result**✗ Failed****Advice** Offside Front Lower Suspension arm has slight play in a ball joint ball joint has lift (2.4.G.2)**Fail** Nearside Windscreen washer provides insufficient washer liquid washer jet missing (8.2.3)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #8** 2015-11-19 14:52**MOT test number** 186844403525**Result** ✓ Passed**MOT #7** 2014-12-03 15:46**MOT test number** 176017934327**Result** ✓ Passed**MOT #6** 2013-12-13 10:12**MOT test number** 516757543319**Result** ✓ Passed

- Notice** Rear assisted suspension faulty not affecting normal leaf suspension
- Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #5 2013-12-13 10:12**MOT test number** 496877943427**Result** ✗ Failed

- Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Rear assisted suspension faulty not affecting normal leaf suspension



MOT #4	2012-12-10 12:54
MOT test number	955655042371
Result	✓ Passed
<div>NoticeRear discs corroded on inner face</div>	
MOT #3	2011-03-03 14:45
MOT test number	899862961097
Result	✓ Passed
MOT #2	2010-02-16 13:07
MOT test number	941907540003
Result	✓ Passed
MOT #1	2009-01-14 11:20
MOT test number	304894219082
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
28 February 2024

✕
MOT

Expired:
22 September 2023

Tax status

Expired at 28 February 2024

Days left

61 days too late

MOT expiry date

22 September 2023

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	KX57BZA
Plate since	2019-09-28
Current registration	KX57BZA
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-01-25
Last registration	2022-09-23
Complete history	See info



Registration #1	2008-01-25	29 mi
Registration #2	2009-01-14	1.373 mi
Registration #3	2010-02-16	2.583 mi
Registration #4	2011-03-03	3.825 mi
Registration #5	2012-12-10	6.446 mi
Registration #6	2013-12-13	11.668 mi
Registration #7	2014-12-03	14.971 mi
Registration #8	2015-11-19	16.541 mi
Registration #9	2017-02-16	18.716 mi
Registration #10	2017-02-17	18.716 mi
Registration #11	2019-05-20	18.716 mi
Registration #12	2019-05-20	18.716 mi
Registration #13	2019-05-20	18.716 mi
Registration #14	2019-05-20	18.716 mi
Registration #15	2019-05-20	18.716 mi
Registration #16	2019-05-20	18.716 mi
Registration #17	2019-05-20	18.716 mi
Registration #18	2019-05-20	18.716 mi
Registration #19	2019-05-20	18.716 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2359 mm
Height	2489 mm
Length	5388 mm
Kerb weight	1887 kg
Max. allowed weight	3300 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	7
Number of axles	2
Engine number	C072496