



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX20 CRDI STYLE
Colour	Grey
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-07-24
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-26
Pictures	28
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-08
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	22
Total items failed	6

MOT #13	2024-04-09 15:30
MOT test number	727219905974
Result	✓ Passed
Next expiry date	2025-04-08

MOT #12	2024-04-09 10:39
MOT test number	550235068037
Result	✗ Failed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
DANGEROUS	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #11	2023-01-09 12:34
MOT test number	670739584159
Result	✓ Passed
Advice	Offside Front Track rod end ball joint has slight play should replace asap (2.1.3 (b) (i))
Advice	Service brake binding but not excessively both side rear (1.2.1 (f))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #10** 2023-01-09 12:34**MOT test number** 641105632693**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Service brake binding but not excessively both side rear (1.2.1 (f))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Track rod end ball joint has slight play should replace asap (2.1.3 (b) (i))**MOT #9** 2022-01-05 14:56**MOT test number** 472269847975**Result** ✓ Passed**MOT #8** 2020-10-22 10:05**MOT test number** 760932135242**Result** ✓ Passed**MOT #7** 2019-12-11 09:35**MOT test number** 157803765897**Result** ✓ Passed**MOT #6** 2018-12-05 11:18**MOT test number** 909630790430**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2018-12-05 11:18**MOT test number** 272316608917**Result** ✗ Failed**Pass with rectification** Nearside Reversing lamp inoperative (4.6.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2017-12-11 08:40**MOT test number** 204777204337**Result** ✓ Passed**MOT #3** 2017-12-11 08:40**MOT test number** 130305319436**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2016-12-07 11:27**MOT test number** 716692406751**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Wiper deteriorating**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Upper Sticker on windscreen within swept area. Not affecting drivers view of the road



MOT #1	2015-12-15 14:31
MOT test number	482781204592
Result	✓ Passed
Advice	Emmision test passed as reading too low register



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
8 April 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	LO62UFP
Plate since	2019-09-29
Current registration	LO62UFP
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-12-21
Last registration	2024-04-09
Complete history	See info



Registration #1	2012-12-21	8 mi
Registration #2	2015-12-15	29.653 mi
Registration #3	2016-12-07	35.974 mi
Registration #4	2017-12-11	41.437 mi
Registration #5	2017-12-11	41.437 mi
Registration #6	2018-12-05	47.958 mi
Registration #7	2018-12-05	47.958 mi
Registration #8	2019-12-11	53.718 mi
Registration #9	2019-12-11	53.718 mi
Registration #10	2019-12-11	53.718 mi
Registration #11	2019-12-11	53.718 mi
Registration #12	2019-12-11	53.718 mi
Registration #13	2019-12-11	53.718 mi
Registration #14	2019-12-11	53.718 mi
Registration #15	2019-12-11	53.718 mi
Registration #16	2019-12-11	53.718 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1380 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBCZ440645