



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 QUIKSILVER
Colour	Grey
Year of manufacture	2005
Top speed	111 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	133 Nm at 3.250 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	166 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-06
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-16
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	34
Total items failed	11

MOT #20	2024-01-17 15:06
MOT test number	211013674940
Result	✓ Passed
Next expiry date	2025-01-16
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Coil spring corroded slight corrosion (5.3.1 (b) (i))

MOT #19	2024-01-17 15:06
MOT test number	991041515153
Result	✗ Failed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Pass with rectification	Exhaust system insecure (6.1.2 (a))
Advice	Nearside Front Coil spring corroded slight corrosion (5.3.1 (b) (i))

**MOT #18**

2022-09-23 15:58

**MOT test number**

900188540252

**Result**

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #17**

2022-09-21 14:40

**MOT test number**

148671967278

**Result**

✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))

**MOT #16** 2021-09-22 14:24**MOT test number** 934951016574**Result** ✓ Passed**MOT #15** 2020-08-01 08:34**MOT test number** 994719778560**Result** ✓ Passed**MOT #14** 2019-04-13 09:40**MOT test number** 288136229548**Result** ✓ Passed**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Fuel tank slightly loose fuel tank mounting strap slightly corroded (6.1.3 (a) (i))**MOT #13** 2018-04-23 15:00**MOT test number** 701612842991**Result** ✓ Passed**MOT #12** 2017-04-15 10:54**MOT test number** 117837970191**Result** ✓ Passed**Advice** Nearside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2016-01-22 13:31**MOT test number** 410457568035**Result** ✓ Passed

**MOT #10** 2016-01-22 13:31**MOT test number** 519946196565**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #9** 2014-11-12 14:51**MOT test number** 505356414366**Result** ✓ Passed**MOT #8** 2013-09-11 11:24**MOT test number** 578574353252**Result** ✓ Passed**Notice** Rear exhaust clamp corroded**Notice** Offside rear tyre out of shape**MOT #7** 2012-09-11 16:50**MOT test number** 369615152426**Result** ✓ Passed**Notice** Oil leak**MOT #6** 2012-09-11 09:53**MOT test number** 919195152299**Result** ✗ Failed**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Notice** Oil leak

**MOT #5** 2011-09-08 16:13**MOT test number** 205681651224**Result** ✓ Passed**MOT #4** 2011-09-08 09:50**MOT test number** 527581151247**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2010-09-20 14:59**MOT test number** 250103460270**Result** ✓ Passed**MOT #2** 2009-09-24 13:36**MOT test number** 582567769201**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2008-10-02 12:38**MOT test number** 733946978282**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
16 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	16 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-28
Last registration	2024-01-17
Complete history	<a href="#">See info</a>



Registration #1	2005-09-28	16 mi
Registration #2	2008-10-02	16.991 mi
Registration #3	2009-09-24	29.210 mi
Registration #4	2010-09-20	41.980 mi
Registration #5	2011-09-08	52.811 mi
Registration #6	2011-09-08	52.811 mi
Registration #7	2012-09-11	64.819 mi
Registration #8	2012-09-11	64.819 mi
Registration #9	2013-09-11	75.101 mi
Registration #10	2014-11-12	82.706 mi
Registration #11	2016-01-22	87.924 mi
Registration #12	2016-01-22	87.924 mi
Registration #13	2016-01-22	87.924 mi
Registration #14	2016-01-22	87.924 mi
Registration #15	2016-01-22	87.924 mi
Registration #16	2016-01-22	87.924 mi
Registration #17	2016-01-22	87.924 mi
Registration #18	2016-01-22	87.924 mi
Registration #19	2016-01-22	87.924 mi
Registration #20	2016-01-22	87.924 mi
Registration #21	2016-01-22	87.924 mi
Registration #22	2016-01-22	87.924 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	NK