



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SPORT
Colour	White
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-27
Pictures	51
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-15
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	24
Total items failed	8

MOT #17 2023-08-16 12:04

MOT test number 586269284866

Result ✓ Passed

Next expiry date 2024-08-15

Advice Central Front Exhaust mounting defective (6.1.2 (a))

Advice Central Front radiator mount corroded

Advice Nearside Rear Nail in tyre

MOT #16 2022-08-15 09:40

MOT test number 328334135541

Result ✓ Passed

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15 2022-08-15 09:40

MOT test number 512384089776

Result ✗ Failed

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

**MOT #14** 2021-08-11 08:25**MOT test number** 510671134585**Result** ✓ Passed**MOT #13** 2021-08-09 14:51**MOT test number** 846739968541**Result** ✗ Failed**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #12** 2020-12-17 14:25**MOT test number** 303461426212**Result** ✓ Passed**Advice** Nearside Front Outer cv boot has a small split**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2020-12-11 14:17**MOT test number** 418976311082**Result** ✗ Failed**Advice** Nearside Front Outer cv boot has a small split**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Position lamp not working sidelight (4.2.1 (a) (ii))

**MOT #10** 2019-12-14 15:26**MOT test number** 982664060571**Result** ✓ Passed**MOT #9** 2018-12-14 09:22**MOT test number** 624404645395**Result** ✓ Passed**MOT #8** 2017-12-14 12:54**MOT test number** 977754626780**Result** ✓ Passed**Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2017-12-09 14:59**MOT test number** 863546335290**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2016-12-13 14:15**MOT test number** 682842638425**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5 2016-12-13 14:15**MOT test number** 166024167971**Result** ✗ Failed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Pass with rectification Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2015-12-01 11:47**MOT test number** 639595347962**Result** ✓ Passed**MOT #3** 2014-11-27 10:34**MOT test number** 525261934380**Result** ✓ Passed**MOT #2** 2013-11-21 11:07**MOT test number** 869095623378**Result** ✓ Passed



MOT #1	2012-11-26 11:36
MOT test number	478871632435
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-12-16
Last registration	2023-08-16
Complete history	See info



Registration #1	2009-12-16	25 mi
Registration #2	2012-11-26	9.830 mi
Registration #3	2013-11-21	18.944 mi
Registration #4	2014-11-27	21.173 mi
Registration #5	2015-12-01	25.009 mi
Registration #6	2016-12-13	31.243 mi
Registration #7	2016-12-13	31.243 mi
Registration #8	2017-12-09	39.929 mi
Registration #9	2017-12-14	40.024 mi
Registration #10	2018-12-14	45.776 mi
Registration #11	2019-05-29	51.557 mi
Registration #12	2019-05-29	51.557 mi
Registration #13	2019-05-29	51.557 mi
Registration #14	2019-05-29	51.557 mi
Registration #15	2019-05-29	51.557 mi
Registration #16	2019-05-29	51.557 mi
Registration #17	2019-05-29	51.557 mi
Registration #18	2019-05-29	51.557 mi
Registration #19	2019-05-29	51.557 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number	156670
---------------	--------