





report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER HARD-TOP TD5
Colour	Green
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Engine capacity	2.495 cc
Cylinders	5
Fuel type	Diesel



CarCheck.co.uk page 1/20




Internet history

Entry 1

Date 2021-07-27

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/20



MOT history

MOT expiry date	2025-03-04
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	107
Total items failed	25

MOT #24	2024-03-05 16:57
MOT test number	593968060242
Result	✓ Passed
Next expiry date	2025-03-04
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #23	2023-01-26 14:18
MOT test number	262646316082
Result	✓ Passed
Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #22	2023-01-25 13:14
MOT test number	585250771820
Result	X Failed
Fail Steering column universal joint has excessive wear or play (2.2.2 (c)) Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #21	2022-01-17 12:16
MOT test number	180023652113
Result	✓ Passed

CarCheck.co.uk page 3/20



MOT #20 2021-07-30 10:16

MOT test number 815966595060

Result \rightarrow Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #19 2020-02-13 17:04

MOT test number 785525433943

Advice Nearside Service brake binding but not excessively (1.2.1 (f))

MOT #18 2020-02-13 11:07

MOT test number 867932790885

Result X Failed

Advice Nearside Service brake binding but not excessively (1.2.1 (f))

Fail Offside Front Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))

Advice Central Exhaust mounting defective (6.1.2 (a))

MOT #17 2019-02-12 16:48

MOT test number 781074212390

Result \(\sqrt{Passed} \)

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Offside Front Seat belt buckle slightly damaged (7.1.2 (d))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/20



MOT #16 2019-02-07 12:41

MOT test number 268932648178

Result X Failed

Pass with rectification

Offside Windscreen wiper does not clear the windscreen effectively Wiper blade.

(3.4 (b) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Front Stub axle has excessive vertical movement between stub axle and axle beam King pin. (5.1.2 (c) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Offside Front Seat belt buckle slightly damaged (7.1.2 (d))

MOT #15 2018-02-08 08:56

MOT test number 845506993250

Result \sqrt{Passed}

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Seat belt cut but webbing not significantly weakened (5.2.2a)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Axle king pin has slight play in pin and/or bush (2.5.A.3a)

Advice Nearside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

Advice Offside Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 5/20



Advice

PN56RUI report date: 2024-03-28

MOT #14 2018-01-31 16:19

MOT test number 204372231327

Result × Failed **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Nearside Front Axle king pin has slight play in pin and/or bush (2.5.A.3a) Offside Front Track rod end ball joint has excessive play (2.2.B.1f) Fail Power steering pump drive system defective (2.3.6) **Fail** Offside Front Seat belt cut but webbing not significantly weakened (5.2.2a) **Advice Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c) Fail Registration plate lamp not working (1.1.C.1d) **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Fail** Central Exhaust has a major leak of exhaust gases (7.1.2) Fail Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4) Nearside Front Seat belt damaged but webbing not significantly weakened (5.2.2a) Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) Advice

Offside Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)

CarCheck.co.uk page 6/20



MOT #13 2017-02-02 15:28

MOT test number 871109571966

	0,11035,1300
Result	✓ Passed
Advice	Offside Front Track rod end ball joint has slight play (2.2.B.1f)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)
Advice	Central Exhaust has a minor leak of exhaust gases (7.1.2)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 7/20



MOT #12 2017-01-27 12:42

MOT test number 509646728137

Result **X** Failed **Advice** Offside Front Brake pad(s) wearing thin (3.5.1g) Fail Power steering component(s) leaking Steering Box (2.3.3b) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a) Advice Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Nearside Front Brake pipe slightly corroded (3.6.B.2c) Advice Fail Nearside Rear Coil spring not correctly located (2.4.C.2) Advice Central Exhaust has a minor leak of exhaust gases (7.1.2) Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Rear Brake pad(s) wearing thin (3.5.1g) Offside Front Track rod end ball joint has slight play (2.2.B.1f) Advice Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Advice Offside Front Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a) Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Offside Front Brake pipe slightly corroded (3.6.B.2c) Advice Nearside Rear Shock absorber has an excessively worn bush (2.7.4) Fail

CarCheck.co.uk page 8/20



MOT #11 2016-01-27 13:42

MOT test number 188980776488

Result \rightarrow Passed

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Power steering component(s) has slight seepage from a seal Steering Box (2.3.3b)

Advice Exhaust corroded in parts

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #10 2016-01-27 13:42

MOT test number 728303626827

Result X Failed

Pass with rectification Offside Rear fog lamp not working (1.3.2b)

Pass with rectification Nearside Rear Shock absorber has an excessively worn bush (2.7.4)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Pass with rectification Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Power steering component(s) has slight seepage from a seal Steering Box (2.3.3b)

Advice Exhaust corroded in parts

CarCheck.co.uk page 9/20



MOT test number

Advice

Advice

Advice

Advice

Advice

PN56RUJ report date: 2024-03-28

918966215045

MOT #9 2015-01-16 14:42

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Shock absorber has a slightly worn bush (2.7.4)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Power steering component(s) has slight seepage from a component (2.3.3b)

Offside Front Brake pipe slightly corroded (3.6.B.2c)

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 10/20



MOT #8

PN56RUJ report date: 2024-03-28

2015-01-15 11:34

MOT test number 457095515034

Fail Offside Rear fog lamp not working (1.3.2b)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Fail Fuel system component leaking (7.2.3)

Advice Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Shock absorber has a slightly worn bush (2.7.4)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Drag link end ball joint has excessive play (2.2.B.1f)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Power steering component(s) has slight seepage from a component (2.3.3b)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 11/20



MOT #7 2014-01-16 11:40

MOT test number 885446914027

Result \sqrt{Passed}

Advice Nearside Drag link end ball joint has slight play (2.2.B.1f)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Power steering component(s) has slight seepage from a component (2.3.3b)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Shock absorber has a slightly worn bush (2.7.4)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Centre Brake pipe slightly corroded (3.6.B.2c)

MOT #6 2013-01-09 12:04

MOT test number 849239403013

Result

Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2013-01-09 12:04

MOT test number 847409403003

Result X Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Fuel system component leaking (7.2.3)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 12/20



Notice

Front & Rear brake pads under half worn

PN56RUJ report date: 2024-03-28

 MOT #4
 2012-01-11 12:27

 MOT test number
 698531112059

 Result
 ✓ Passed

 MOT #3
 2010-10-11 12:41

 MOT test number
 231444480220

 Result
 ✓ Passed

 Notice
 Rear brake discs pitted

MOT #2 2010-10-11 12:41 **MOT test number** 310684180296 Result × Failed **Notice** Rear brake discs pitted **Pass with rectification** Offside Rear fog lamp not working (1.3.2b) **Pass with rectification** Offside Rear Lower Shock absorber has an excessively worn bush (2.7.4) Notice Front & Rear brake pads under half worn **Pass with rectification** Nearside Rear Lower Shock absorber has an excessively worn bush (2.7.4)

MOT #1	2009-09-22 09:20
MOT test number	534565869290
Result	✓ Passed

CarCheck.co.uk page 13/20



Tax & MOT check



CarCheck.co.uk page 14/20




Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 15/20



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 16/20



Owner	hictor.
UMMIAI	nisiaiv

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download	
2000000	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	AK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 17/20



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 18/20



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-09-26
Last registration	2024-03-05
Complete history	See info



Registration #1	2006-09-26	19 mi
Registration #2	2009-09-22	24.972 mi
Registration #3	2010-10-11	34.286 mi
Registration #4	2012-01-11	44.978 mi
Registration #5	2013-01-09	51.480 mi
Registration #6	2014-01-16	58.289 mi
Registration #7	2015-01-15	65.563 mi
Registration #8	2015-01-16	65.567 mi
Registration #9	2016-01-27	73.780 mi
Registration #10	2016-01-27	73.780 mi
Registration #11	2017-01-27	80.690 mi
Registration #12	2017-02-02	80.844 mi
Registration #13		11.117 es
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		71.777 es
Registration #18		71.777 es
Registration #19		71.777 es
Registration #20		71.777 es
Registration #21		71,777 66
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es

More info >



Dimensions & weight

Width	1790 mm
Height	2076 mm
Length	3883 mm
Kerb weight	1740 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	5
Number of axles	2
Engine number	15P20995B

CarCheck.co.uk page 20/20