



SYIIBN

report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Red
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 4

Date	2023-02-13
Pictures	0
Listing price	<a href="#">View report</a>

source: carcraft.co.uk

Entry 3


Date	2022-12-11
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 2


Date	2022-12-08
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](http://autoonline.co.uk)



## MOT history

MOT expiry date	2024-12-07
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	13
Total items failed	4

MOT #14	2023-11-23 14:44
MOT test number	288137520033
Result	✓ Passed
Next expiry date	2024-12-07

MOT #13	2022-12-08 10:44
MOT test number	112601449480
Result	✓ Passed

MOT #12	2022-03-02 11:35
MOT test number	248568543533
Result	✓ Passed

**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #11	2021-03-01 11:54
MOT test number	131149195325
Result	✓ Passed

MOT #10	2020-04-20 13:36
MOT test number	229674765196
Result	✓ Passed

**MOT #9** 2020-04-20 08:34**MOT test number** 218239816909**Result** ✗ Failed

**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #8** 2019-04-16 12:07**MOT test number** 927333972177**Result** ✓ Passed**MOT #7** 2018-04-17 06:17**MOT test number** 564304927235**Result** ✓ Passed**MOT #6** 2017-04-18 08:45**MOT test number** 319151291439**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2016-04-21 13:03**MOT test number** 236268170438**Result** ✓ Passed

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Undertrays fitted restricting view to some components

**MOT #4** 2015-06-26 15:15**MOT test number** 489337075172**Result** ✓ Passed



<b>MOT #3</b>	2015-06-26 13:11
<b>MOT test number</b>	257817775489
<b>Result</b>	✗ Failed
<b>Fail</b>	Brake pedal anti-slip provision missing (3.3.A.1b)

<b>MOT #2</b>	2014-06-30 17:23
<b>MOT test number</b>	898611984176
<b>Result</b>	✓ Passed
<b>Notice</b>	Engine covers fitted obscuring some components in the engine bay
<b>Advice</b>	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Notice</b>	Under-trays fitted obscuring some underside components
<b>Notice</b>	Nail in nearside rear tyre

<b>MOT #1</b>	2014-06-30 15:28
<b>MOT test number</b>	868201184183
<b>Result</b>	✗ Failed
<b>Notice</b>	Under-trays fitted obscuring some underside components
<b>Advice</b>	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Notice</b>	Nail in nearside rear tyre
<b>Notice</b>	Engine covers fitted obscuring some components in the engine bay
<b>Fail</b>	Brake pedal anti-slip provision missing (3.3.A.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
7 December 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	7 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>SY11YBN</b>
Plate since	2024-03-29
Current registration	<b>SY11YBN</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-06-29
Last registration	2023-11-23
Complete history	<a href="#">See info</a>



Registration #1	2011-06-29	16 mi
Registration #2	2014-06-30	22.540 mi
Registration #3	2014-06-30	22.540 mi
Registration #4	2015-06-26	31.637 mi
Registration #5	2015-06-26	31.637 mi
Registration #6	2016-04-21	35.307 mi
Registration #7	2017-04-18	39.261 mi
Registration #8	2018-04-17	46.486 mi
Registration #9	2019-04-16	52.788 mi
Registration #10	2020-04-20	58.697 mi
Registration #11	2020-04-20	58.697 mi
Registration #12	2020-04-20	58.697 mi
Registration #13	2020-04-20	58.697 mi
Registration #14	2020-04-20	58.697 mi
Registration #15	2020-04-20	58.697 mi
Registration #16	2020-04-20	58.697 mi
Registration #17	2020-04-20	58.697 mi
Registration #18	2020-04-20	58.697 mi
Registration #19	2020-04-20	58.697 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1891 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1017784