



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 1700 CDTI
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-04
Pictures	15
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-01-04
MOT pass rate	52 %
MOT passed	11
Failed MOT tests	10
Total advice items	55
Total items failed	21

MOT #21 2023-12-29 08:41

MOT test number 918651014320

Result ✓ Passed

Next expiry date 2025-01-04

- Advice** Oil leak, but not excessive sump level sensor (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both disc's corroded and worn (1.1.14 (a) (ii))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #20 2023-12-29 08:41

MOT test number 210211989982

Result ✗ Failed

- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both disc's corroded and worn (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive sump level sensor (8.4.1 (a) (i))
- Pass with rectification** Nearside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen jet blocked (3.5 (a))

**MOT #19**

2023-01-05 11:12

MOT test number

646881251241

Result

✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Registration plate lamp throwing direct white light to the rear (4.7.1 (a))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18

2021-10-07 15:51

MOT test number

732498826908

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2021-10-07 13:40

MOT test number

449365652912

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16**

2020-12-02 16:22

MOT test number

873588977617

Result**✓ Passed****Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #15

2020-12-02 15:36

MOT test number

726620192423

Result		✗ Failed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Service light on	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Minor	Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

**MOT #14**

2020-11-25 15:00

MOT test number

520651224243

Result

✗ Failed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Service light on
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #13

2019-06-28 08:17

MOT test number

884343464538

Result

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12

2018-07-25 14:47

MOT test number

383838702307

Result

✓ Passed

**MOT #11** 2018-07-20 14:23**MOT test number** 161578893013**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Reversing lamp inoperative (4.6.1 (a))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #10** 2017-07-26 12:47**MOT test number** 813976774026**Result** ✓ Passed**MOT #9** 2017-07-26 08:49**MOT test number** 464993347890**Result** ✗ Failed**Fail** Rear parking (secondary) brakes imbalanced Os slow 37% imbalance (3.7.B.6b)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Rear Exhaust has a major leak of exhaust gases Box (7.1.2)**MOT #8** 2016-07-26 10:50**MOT test number** 188725211739**Result** ✓ Passed**MOT #7** 2016-07-26 08:08**MOT test number** 352348575622**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure Inner (4.1.D.1b)

**MOT #6** 2015-07-27 12:26**MOT test number** 317748605492**Result** ✓ Passed**MOT #5** 2015-07-27 11:59**MOT test number** 255608605263**Result** ✗ Failed**Fail** Horn not working (1.6.2a)**MOT #4** 2014-06-30 09:38**MOT test number** 185291784186**Result** ✓ Passed**Notice** Oil leak**MOT #3** 2014-06-27 10:27**MOT test number** 339098174103**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Oil leak**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2013-07-22 09:15**MOT test number** 145263003264**Result** ✓ Passed**Notice** Os wiper slightly worn



MOT #12013-07-08 10:00

MOT test number878189183177

Result

Failed

- Fail

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail

Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)
- Fail

Nearside Headlamp not working on dipped beam (1.7.5a)
- Notice

Os wiper slightly worn



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
4 January 2025

Tax status	Valid until 1 January
-------------------	-----------------------

Days left	247
------------------	-----

MOT expiry date	4 January 2025
------------------------	----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	BT10VEW
Plate since	2019-09-29
Current registration	BT10VEW
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2010-07-23
Last registration	2023-12-29
Complete history	See info



Registration #1	2010-07-23	28 mi
Registration #2	2013-07-08	51.702 mi
Registration #3	2013-07-22	52.756 mi
Registration #4	2014-06-27	74.549 mi
Registration #5	2014-06-30	74.633 mi
Registration #6	2015-07-27	79.452 mi
Registration #7	2015-07-27	79.452 mi
Registration #8	2016-07-26	83.593 mi
Registration #9	2016-07-26	83.594 mi
Registration #10	2017-07-26	84.755 mi
Registration #11	2017-07-26	84.755 mi
Registration #12	2018-07-20	86.336 mi
Registration #13	2019-06-20	88.336 mi
Registration #14	2019-06-20	88.336 mi
Registration #15	2019-06-20	88.336 mi
Registration #16	2019-06-20	88.336 mi
Registration #17	2019-06-20	88.336 mi
Registration #18	2019-06-20	88.336 mi
Registration #19	2019-06-20	88.336 mi
Registration #20	2019-06-20	88.336 mi
Registration #21	2019-06-20	88.336 mi
Registration #22	2019-06-20	88.336 mi
Registration #23	2019-06-20	88.336 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1210 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	3674463