




report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA DIAMOND CDTI S/S
Colour	Black
Year of manufacture	2014
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-03-05
Pictures	0
Listing price	View report

source: yesauto.com



MOT history

MOT expiry date	2025-01-09
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	9
Total items failed	4

MOT #10	2023-12-27 09:30
MOT test number	607004901470
Result	✓ Passed
Next expiry date	2025-01-09
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9	2022-12-30 12:57
MOT test number	352901877709
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8	2022-12-30 09:56
MOT test number	933611225408
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #7** 2021-12-29 16:14**MOT test number** 558261366152**Result** ✓ Passed**MOT #6** 2020-12-16 11:56**MOT test number** 178870696798**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #5** 2019-12-19 11:13**MOT test number** 876233077580**Result** ✓ Passed**MOT #4** 2018-12-17 14:41**MOT test number** 385815805012**Result** ✓ Passed**MOT #3** 2018-12-17 14:41**MOT test number** 583510607074**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Central Rear Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #2** 2017-12-18 12:18**MOT test number** 798783226505**Result** ✓ Passed



MOT #1	2016-12-13 13:10
MOT test number	142975835509
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
9 January 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	9 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VN63PUV
Plate since	2019-06-29
Current registration	 VN63PUV
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-01-10
Last registration	2023-12-27
Complete history	See info



Registration #1	2014-01-10	10 mi
Registration #2	2016-12-13	18.060 mi
Registration #3	2017-12-18	22.670 mi
Registration #4	2018-12-17	27.785 mi
Registration #5	2018-12-17	27.785 mi
Registration #6	2019-12-19	32.660 mi
Registration #7	2019-12-19	32.660 mi
Registration #8	2019-12-19	32.660 mi
Registration #9	2019-12-19	32.660 mi
Registration #10	2019-12-19	32.660 mi
Registration #11	2019-12-19	32.660 mi
Registration #12	2019-12-19	32.660 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 300287K LNQ