



**BG55POU**

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BORA S TDI (90BHP)
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	210 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg







Internet history

Entry 1

Date	2021-06-25
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #16** 2021-10-01 10:40**MOT test number** 871101890980**Result** ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Headlamp lens seriously defective faded no beam image (4.1.1 (b) (ii))**MAJOR** Emissions not tested rear box missing (8.2.2.2 (e))**MAJOR** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Nearside Front Tyre obviously under inflated (5.2.3 (I))**MAJOR** Nearside Front Headlamp lens seriously defective faded no beam image (4.1.1 (b) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Exhaust fumes entering cabin (6.1.2 (b) (i))**MAJOR** Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition (8.1.1 (a))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #15** 2021-01-29 14:46**MOT test number** 269587205945**Result** ✓ Passed**MOT #14** 2020-02-01 12:57**MOT test number** 944107880243**Result** ✓ Passed

**MOT #13** 2020-02-01 12:12**MOT test number** 483016795274**Result** ✗ Failed**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #12** 2018-09-12 08:26**MOT test number** 443653099650**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front wheel arch liner damaged**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin very low (1.1.13 (a) (ii))**MOT #11** 2017-09-06 08:55**MOT test number** 384848534997**Result** ✓ Passed**Advice** ALL tyres cracking and rear tyres wearing uneven**MOT #10** 2016-09-08 11:11**MOT test number** 980246544240**Result** ✓ Passed**MOT #9** 2016-09-08 08:17**MOT test number** 107141382636**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



<b>MOT #8</b>	2015-09-11 09:07
---------------	------------------

<b>MOT test number</b>	558594231727
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside front tyre sidewall cracking curb damage
---------------	---

<b>Advice</b>	Drivers door stiff to open(intermitant)
---------------	---

<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)
---------------	--

<b>MOT #7</b>	2014-09-02 13:15
---------------	------------------

<b>MOT test number</b>	298955144267
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2013-09-10 10:40
---------------	------------------

<b>MOT test number</b>	938633053206
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2012-09-11 09:20
---------------	------------------

<b>MOT test number</b>	578325952255
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2011-09-13 09:56
---------------	------------------

<b>MOT test number</b>	957166351281
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2010-09-13 15:16
---------------	------------------

<b>MOT test number</b>	551266650268
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2009-09-14 13:14
---------------	------------------

<b>MOT test number</b>	712317459201
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #1	2008-09-23 12:22
MOT test number	700787468265
Result	✓ Passed



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BG55POU</b>
Plate since	2024-03-29
Current registration	 <b>BG55POU</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-10-20
Last registration	2021-10-01
Complete history	<a href="#">See info</a>



Registration #1	2005-10-20	20 mi
Registration #2	2008-09-23	14.442 mi
Registration #3	2009-09-14	19.122 mi
Registration #4	2010-09-13	23.868 mi
Registration #5	2011-09-13	26.569 mi
Registration #6	2012-09-11	28.887 mi
Registration #7	2013-09-10	31.544 mi
Registration #8	2014-09-02	34.120 mi
Registration #9	2015-09-11	38.231 mi
Registration #10	2016-09-11	42.342 mi
Registration #11	2017-09-11	46.453 mi
Registration #12	2018-09-11	50.564 mi
Registration #13	2019-09-11	54.675 mi
Registration #14	2020-09-11	58.786 mi
Registration #15	2021-09-11	62.897 mi
Registration #16	2022-09-11	67.008 mi
Registration #17	2023-09-11	71.119 mi
Registration #18	2024-09-11	75.230 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2018 mm
Height	1446 mm
Length	4376 mm
Wheel base	2519 mm
Kerb weight	1275 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Engine number	ATD684816