



report date: 2024-03-29

## General information

Make	VOLVO
Model	V70 D SE
Colour	Silver
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-17
Pictures	32
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-08-04
<b>MOT pass rate</b>	92 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	17
<b>Total items failed</b>	2

**MOT #12** 2023-08-03 08:23**MOT test number** 870587365302**Result** Passed**Next expiry date** 2024-08-04

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Front Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #11** 2022-08-05 13:29**MOT test number** 171144329002**Result** Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10** 2021-07-28 11:41**MOT test number** 307369072414**Result** ✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Under trays fitted not all components can be fully inspected

**MOT #9** 2020-09-02 08:00**MOT test number** 953397358457**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-09-14 16:53**MOT test number** 734126930269**Result** ✓ Passed**MOT #7** 2017-08-31 09:15**MOT test number** 466868794189**Result** ✓ Passed

- Advice** Offside Front tyre worn bald inside
- Advice** Nearside Front tyre worn bald inside
- Advice** Eml on dash

**MOT #6** 2017-06-02 09:09**MOT test number** 966847657107**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-08-03 15:33**MOT test number** 818007716763**Result** ✓ Passed**Advice** Both rear tyres 3mm tread and r/o/s tyre split in tread**MOT #4** 2015-06-25 10:14**MOT test number** 408576275150**Result** ✓ Passed**MOT #3** 2011-05-05 13:37**MOT test number** 889665721178**Result** ✓ Passed**MOT #2** 2011-03-10 14:39**MOT test number** 308649161008**Result** ✓ Passed**MOT #1** 2011-03-10 12:27**MOT test number** 829159361073**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
4 August 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	4 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-05-08
Last registration	2023-08-03
Complete history	<a href="#">See info</a>



Registration #1	2008-05-08	26 mi
Registration #2	2011-03-10	46.389 mi
Registration #3	2011-03-10	46.389 mi
Registration #4	2011-05-05	48.636 mi
Registration #5	2015-06-25	99.865 mi
Registration #6	2016-08-03	111.282 mi
Registration #7	2017-08-31	120.320 mi
Registration #8	2019-05-29	120.320 mi
Registration #9	2019-05-29	120.320 mi
Registration #10	2019-05-29	120.320 mi
Registration #11	2019-05-29	120.320 mi
Registration #12	2019-05-29	120.320 mi
Registration #13	2023-08-03	120.320 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1804 mm
Height	1465 mm
Length	4710 mm
Wheel base	2816 mm
Kerb weight	1761 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	528834