



report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO MULTIJET MYLIFE
Colour	White
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 2.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-22
Pictures	20
Listing price	View report



Choice Of Many More
LOW INSURANCE
Cars In Stock
Visit Our Website For More Info
www.assuredcarssupermarket.co.uk
46 Stony Lane, Birmingham, B128AF (0121 606 4041)

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-15
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	28
Total items failed	15

MOT #14 2023-08-15 12:53

MOT test number 579652643322

Result ✓ Passed

Next expiry date 2024-08-15

- Minor** Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake disc worn, but not excessively both rear (1.1.14 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Front Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Brake disc worn, but not excessively both front (1.1.14 (a) (i))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13 2022-08-12 16:20

MOT test number 621218820385

Result ✓ Passed

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))



MOT #12	2021-08-16 14:38
MOT test number	327196786175
Result	✓ Passed

MOT #11	2021-08-14 10:49
MOT test number	978467248388
Result	✗ Failed

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))



MOT #10

2021-07-21 11:53

MOT test number

515855035366

Result

✗ Failed

- Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Rear exhaust silencer corroded
- Advice

Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Pass with rectification

Nearside Headlamp aim too high (4.1.2 (a))
- Advice

Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail

Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Fail

Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Items removed from driver's view prior to test
- Pass with rectification

Offside Headlamp aim too high (4.1.2 (a))
- Advice

Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #9** 2021-07-16 11:59**MOT test number** 740063242703**Result** ✗ Failed**Fail** Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Exhaust back-box outer shield corroded**MOT #8** 2020-07-23 12:58**MOT test number** 750850651735**Result** ✓ Passed**MOT #7** 2020-07-23 10:47**MOT test number** 244033106177**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #6** 2019-08-06 09:34**MOT test number** 146409476467**Result** ✓ Passed

**MOT #5** 2019-08-05 08:53**MOT test number** 467785153644**Result** ✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (ii))
- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Front subframe corroded

MOT #4 2018-12-12 09:27**MOT test number** 373879672068**Result** ✓ Passed

- Advice** Front tyres worn on edges
- Advice** Rear exhaust deteriorated

MOT #3 2017-12-18 09:10**MOT test number** 354901397472**Result** ✓ Passed**MOT #2** 2016-11-25 14:40**MOT test number** 770719165571**Result** ✓ Passed**MOT #1** 2015-12-21 11:43**MOT test number** 475666507048**Result** ✓ Passed

- Advice** Offside Front nail in tyre



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-12-21
Last registration	2023-08-15
Complete history	See info



Registration #1	2012-12-21	23 mi
Registration #2	2015-12-21	24.916 mi
Registration #3	2016-11-25	35.223 mi
Registration #4	2017-12-18	49.758 mi
Registration #5	2018-12-12	64.656 mi
Registration #6	2019-08-05	76.762 mi
Registration #7	2019-08-06	76.762 mi
Registration #8	2020-07-23	87.063 mi
Registration #9	2020-08-20	98.377 mi
Registration #10	2020-09-17	109.691 mi
Registration #11	2020-10-14	121.005 mi
Registration #12	2020-11-11	132.319 mi
Registration #13	2020-12-08	143.633 mi
Registration #14	2021-01-05	154.947 mi
Registration #15	2021-02-02	166.261 mi
Registration #16	2021-02-26	177.575 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	6823860
---------------	---------