



LS10JZX

report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ2
Colour	Blue
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	91 BHP
Max. torque	116 Nm at 4.200 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 2


Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	15
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-08-30
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	22
Total items failed	1

MOT #14	2023-08-31 13:56
MOT test number	623183065390
Result	✓ Passed
Next expiry date	2024-08-30
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13	2023-08-31 13:56
MOT test number	128858757584
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #12** 2022-08-03 11:29**MOT test number** 218980296003**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**MOT #11** 2021-08-02 17:11**MOT test number** 613259999562**Result** ✓ Passed**MOT #10** 2021-08-02 08:17**MOT test number** 587263555495**Result** ✗ Failed**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #9** 2020-08-04 15:29**MOT test number** 471549422268**Result** ✓ Passed**MOT #8** 2020-08-03 10:26**MOT test number** 900261145266**Result** ✗ Failed**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))

**MOT #7** 2019-03-26 09:31**MOT test number** 758152358994**Result** ✓ Passed**Advice** N/S/R brake squeal when spinning / turning wheel slowly.**Advice** Tyre slightly damaged/cracking or perishing Both front perishing in tread. (5.2.3 (d) (ii))**MOT #6** 2018-03-21 09:33**MOT test number** 355493654101**Result** ✓ Passed**Advice** Front tyres perishing.**Advice** Brake pad(s) wearing thin Front (3.5.1g)**MOT #5** 2017-03-07 09:59**MOT test number** 150629676497**Result** ✓ Passed**MOT #4** 2016-03-29 10:49**MOT test number** 441345569458**Result** ✓ Passed**Advice** BOTH REAR TYRES CRACKING IN TREADS.**MOT #3** 2015-03-03 10:08**MOT test number** 439132065007**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #2	2014-03-28 09:14
MOT test number	877267284047
Result	✓ Passed
<div>Notice</div> Rear tyres are cracked/perished	

MOT #1	2013-03-27 09:09
MOT test number	759656583040
Result	✓ Passed
<div>Notice</div> All four tyres cracking	



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
30 August 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-31
Last registration	2023-08-31
Complete history	See info



Registration #1	2010-03-31	23 mi
Registration #2	2013-03-27	24.329 mi
Registration #3	2014-03-28	29.581 mi
Registration #4	2015-03-03	32.318 mi
Registration #5	2016-03-29	36.942 mi
Registration #6	2017-03-07	42.488 mi
Registration #7	2018-03-21	45.934 mi
Registration #8	2019-03-26	51.635 mi
Registration #9	2020-08-03	55.852 mi
Registration #10	2021-08-03	59.377 mi
Registration #11	2022-08-03	62.902 mi
Registration #12	2023-08-31	66.427 mi
Registration #13	2024-03-29	70.952 mi
Registration #14	2024-03-29	74.477 mi
Registration #15	2024-03-29	78.002 mi
Registration #16	2024-03-29	81.527 mi
Registration #17	2024-03-29	85.052 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1590 mm
Length	3760 mm
Wheel base	2380 mm
Kerb weight	970 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-2226353