



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Silver
Year of manufacture	-
Top speed	129 mph
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg



LABEL UNKNOWN

**MOT history****MOT #14** 2020-03-05 15:47**MOT test number** 235791402148**Result** ✓ Passed**Next expiry date** 2021-03-06

- Advice** Nearside Front Tyre slightly damaged Outer Side Wall (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13 2020-03-02 09:22**MOT test number** 673832475904**Result** ✗ Failed

- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Front Tyre slightly damaged Outer Side Wall (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2019-03-07 12:44**MOT test number** 777601242387**Result** ✓ Passed**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #11** 2018-03-05 11:04**MOT test number** 473192500764**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2017-02-13 16:52**MOT test number** 666537162749**Result** ✓ Passed**Advice** Exhaust system corroded**Advice** Offside rear brake pads wearing low**Advice** Some insecurity of battery**Advice** Some binding of offside rear brake**Advice** Wiper blades split**MOT #9** 2016-01-30 10:50**MOT test number** 638313788386**Result** ✓ Passed

**MOT #8** 2015-12-01 16:30**MOT test number** 337214046725**Result** ✗ Failed**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Battery slightly insecure**Fail** Offside Rear rear brake binding (3.7.B.1)**Advice** Both rear tyres perishing**MOT #7** 2014-11-20 12:56**MOT test number** 959014724346**Result** ✓ Passed**Advice** Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #6**

2014-11-19 17:32

MOT test number

429503824434

Result

✗ Failed

- Advice** Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Fail** Rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Rear brake binding (3.7.B.1)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Fail** Offside front brake binding (3.7.B.1)

MOT #5

2014-01-07 13:09

MOT test number

839707604064

Result

✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Exhaust worn



MOT #4	2012-11-28 14:59
---------------	------------------

MOT test number	415663632361
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2011-12-19 15:48
---------------	------------------

MOT test number	868023251386
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-04-18 09:00
---------------	------------------

MOT test number	968548501136
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	OFFSIDE REAR TYRE HAS CRACKING ON INNER SIDE WALL THAT REQUIRES CHECKING . NO CORDS VISIBLE AT TIME OF TEST
---------------	---

Notice	Nail in nearside rear tyre
---------------	----------------------------

MOT #1	2010-03-17 10:29
---------------	------------------

MOT test number	560916570030
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-03-22
Last registration	2020-03-05
Complete history	See info



Registration #1	2007-03-22	11 mi
Registration #2	2010-03-17	27.003 mi
Registration #3	2011-04-18	37.409 mi
Registration #4	2011-12-19	39.079 mi
Registration #5	2012-11-28	49.809 mi
Registration #6	2014-01-07	59.015 mi
Registration #7	2014-11-19	61.881 mi
Registration #8	2014-11-20	61.881 mi
Registration #9	2015-05-20	61.881 mi
Registration #10	2015-05-20	61.881 mi
Registration #11	2015-05-20	61.881 mi
Registration #12	2015-05-20	61.881 mi
Registration #13	2015-05-20	61.881 mi
Registration #14	2015-05-20	61.881 mi
Registration #15	2015-05-20	61.881 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1342 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC6748123