



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 DRIVE SE START/STOP
Colour	Red
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-07-05
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-12
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	13
Total items failed	5

MOT #14	2023-07-13 09:51
MOT test number	228526928349
Result	✓ Passed
Next expiry date	2024-07-12
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #13	2023-07-10 12:05
MOT test number	809696844310
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm 235-40-18 flat spot bald (5.2.3 (e))
Advice	Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #12	2022-06-30 13:23
MOT test number	852756790634
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2021-07-08 16:14**MOT test number** 400992938266**Result** ✓ Passed**MOT #10** 2020-10-30 16:25**MOT test number** 869160496935**Result** ✓ Passed**MOT #9** 2020-10-30 16:25**MOT test number** 847812013116**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #8** 2019-10-21 07:36**MOT test number** 650889722573**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt n/s and o/s**MOT #7** 2018-10-19 10:55**MOT test number** 591665437954**Result** ✓ Passed**MOT #6** 2018-10-19 10:55**MOT test number** 212347956489**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #5** 2017-10-23 08:37**MOT test number** 165432713723**Result** ✓ Passed

**MOT #4** 2017-01-07 09:42**MOT test number** 839067290004**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #3** 2017-01-07 09:42**MOT test number** 626479792758**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2016-01-15 16:19**MOT test number** 521895605140**Result** ✓ Passed**Advice** Emissions too low to read**Advice** Nail in osr tyre**MOT #1** 2015-06-22 12:07**MOT test number** 447353975186**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
12 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-06-26
Last registration	2023-07-13
Complete history	See info



Registration #1	2012-06-26	10 mi
Registration #2	2015-06-22	28.780 mi
Registration #3	2016-01-15	29.684 mi
Registration #4	2017-01-07	34.854 mi
Registration #5	2017-01-07	34.854 mi
Registration #6	2017-10-23	37.218 mi
Registration #7	2018-10-19	40.585 mi
Registration #8	2018-10-19	40.585 mi
Registration #9	2019-06-20	41.277 mi
Registration #10	2019-06-20	41.277 mi
Registration #11	2019-06-20	41.277 mi
Registration #12	2019-06-20	41.277 mi
Registration #13	2019-06-20	41.277 mi
Registration #14	2019-06-20	41.277 mi
Registration #15	2019-06-20	41.277 mi
Registration #16	2019-06-20	41.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1582 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4130882