



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D4 R-DESIGN NAV
Colour	Grey
Year of manufacture	2015
Top speed	130 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	400 Nm at 2.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 3

Date	2022-09-04
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2



Date	2021-10-27
Pictures	4
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-06-14
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-07
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	22
Total items failed	5

MOT #9	2023-09-04 12:48
MOT test number	367633545132
Result	✓ Passed
Next expiry date	2024-09-07
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

MOT #8	2022-09-08 13:20
MOT test number	705290250794
Result	✓ Passed

MOT #7	2021-08-24 16:19
MOT test number	296961187894
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Uneven tyre wear

**MOT #6** 2021-08-24 11:28**MOT test number** 958913990588**Result** ✗ Failed

- Advice** Uneven tyre wear
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Nearside Rear tyre flat
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2020-08-21 16:26**MOT test number** 870368922290**Result** ✓ Passed

- Advice** Engine bay covers / undertrays fitted not allowing full inspection
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2020-08-21 10:11**MOT test number** 437287974522**Result** ✗ Failed

- Fail** Nearside Front Position lamp likely to become detached (4.2.1 (c) (ii))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Engine bay covers / undertrays fitted not allowing full inspection
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #3	2019-08-23 09:18
MOT test number	589170759401
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #2	2018-08-16 13:22
MOT test number	640169160298
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords multiple places in tread (5.2.3 (d) (i))
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (i))

MOT #1	2018-08-16 09:59
MOT test number	938132637903
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides scored from brake pads being on the metal (1.1.14 (a) (ii))
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords multiple places in tread (5.2.3 (d) (i))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
7 September 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DK65TWF
Plate since	2024-03-29
Current registration	DK65TWF
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-09-01
Last registration	2023-09-04
Complete history	See info



Registration #1	2015-09-01	11 mi
Registration #2	2018-08-16	46.301 mi
Registration #3	2018-08-16	46.302 mi
Registration #4	2019-08-23	63.229 mi
Registration #5	2020-08-21	81.396 mi
Registration #6	2020-08-21	81.396 mi
Registration #7	2023-09-04	81.396 mi
Registration #8	2023-09-04	81.396 mi
Registration #9	2023-09-04	81.396 mi
Registration #10	2023-09-04	81.396 mi
Registration #11	2023-09-04	81.396 mi
Registration #12	2023-09-04	81.396 mi
Registration #13	2023-09-04	81.396 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1747 kg
Max. allowed weight	2485 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

1216733