



report date: 2024-03-28

General information

Make	AUDI
Model	A4 TDI DPF S LINE
Colour	Grey
Year of manufacture	2010
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-06-16
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-02
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	18
Total items failed	9

MOT #18	2024-02-03 12:31
MOT test number	410828400993
Result	✓ Passed
Next expiry date	2025-02-02

MOT #17	2024-02-03 11:47
MOT test number	980968725877
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #16	2023-01-28 15:01
MOT test number	525149145714
Result	✓ Passed

MOT #15	2022-01-31 17:42
MOT test number	459798164300
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2022-01-31 14:41**MOT test number** 504922111995**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #13** 2021-02-01 14:16**MOT test number** 939176145760**Result** ✓ Passed**MOT #12** 2021-02-01 12:45**MOT test number** 622169819433**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11** 2019-06-24 10:20**MOT test number** 747407347049**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-06-13 13:04**MOT test number** 639489936207**Result** ✓ Passed

**MOT #9** 2018-06-11 13:12**MOT test number** 134476421208**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Suspension arm ball joint excessively worn suspension arm forward most of the 2 (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2017-11-03 08:49**MOT test number** 301715879232**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Plastic under-trays fitted**MOT #7** 2016-11-07 17:08**MOT test number** 462820580029**Result** ✓ Passed**MOT #6** 2016-02-25 13:03**MOT test number** 461602985191**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2015-03-02 09:39**MOT test number** 936381165033**Result** ✓ Passed

**MOT #4** 2014-03-10 14:27**MOT test number** 749359264043**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-03-10 09:49**MOT test number** 689999464020**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Side repeater not working (1.4.A.2c)**MOT #2** 2013-02-27 12:49**MOT test number** 106238153067**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-02-27 09:34**MOT test number** 169338553089**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
2 February 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	2 February 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-15
Last registration	2024-02-03
Complete history	<a href="#">See info</a>



Registration #1	2010-03-15	10 mi
Registration #2	2013-02-27	26.365 mi
Registration #3	2013-02-27	26.365 mi
Registration #4	2014-03-10	34.604 mi
Registration #5	2014-03-10	34.608 mi
Registration #6	2015-03-02	43.533 mi
Registration #7	2016-02-25	51.119 mi
Registration #8	2016-11-07	55.405 mi
Registration #9	2017-11-03	62.793 mi
Registration #10	2018-06-11	66.373 mi
Registration #11	2019-05-29	70.377 mi
Registration #12	2019-05-29	70.377 mi
Registration #13	2019-05-29	70.377 mi
Registration #14	2019-05-29	70.377 mi
Registration #15	2019-05-29	70.377 mi
Registration #16	2019-05-29	70.377 mi
Registration #17	2019-05-29	70.377 mi
Registration #18	2019-05-29	70.377 mi
Registration #19	2019-05-29	70.377 mi
Registration #20	2019-05-29	70.377 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1854 mm
Height	1372 mm
Length	4625 mm
Wheel base	2751 mm
Kerb weight	1470 kg
Max. allowed weight	1975 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	CAH 129958