



PEUGEOT



DUI2DWM

report date: 2024-03-28

General information

Make	PEUGEOT
Model	BIPPER HDI S
Colour	Grey
Year of manufacture	2012
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	72.4 mpg
Consumption combined	61.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-22
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2023-10-25
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	44
Total items failed	20

MOT #12	2022-10-26 14:22
---------	------------------

MOT test number	579249512897
-----------------	--------------

Result	✓ Passed
Next expiry date	2023-10-25
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Windscreen wiper blade defective (3.4 (b) (i))
Advice	Offside Front Driver door handle slightly broken
Advice	Rear Coil spring corroded Both sides (5.3.1 (b) (i))
Advice	Suspension component corroded but not seriously weakened Both front and rear (5.3.3 (b) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
Minor	Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Side repeater insecure slightly damaged.
Advice	Front Headlamp has a product on the lens but not seriously reducing light output Both sides (4.1.4 (b))



MOT #112021-11-11 16:19

MOT test number299193496141

Result

✓ Passed

- Advice

Clutch pedal rubber missing
- Advice

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice

Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users vapour (8.2.2.2 (c))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Nearside Front Play in steering rack inner joint(s)
- Advice

Bonnet damaged
- Advice

Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice

Rear Coil spring corroded both (5.3.1 (b) (i))

**MOT #10**

2021-11-09 14:24

**MOT test number**

189564362060

**Result****✗ Failed****Advice** Nearside Front Play in steering rack inner joint(s)**Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Brake fluid significantly below minimum mark (1.1.10 (d) (ii))**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Clutch pedal rubber missing**Fail** Nearside Front Road wheel badly distorted (5.2.2 (c) (i))**Fail** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users vapour (8.2.2.2 (c))**Fail** Nearside Oil leaking excessively from transmission transmission (8.4.1 (a) (i))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Bonnet damaged**Advice** Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Fail** Brake pedal anti-slip provision missing (1.1.2 (c))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #9** 2020-11-27 11:27**MOT test number** 441239997075**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**MOT #8** 2019-05-24 10:02**MOT test number** 549942794104**Result** ✓ Passed**MOT #7** 2019-05-23 10:09**MOT test number** 130652858723**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Nearside Front Direction indicator not working (4.4.1 (a) (ii))**MOT #6** 2018-05-16 14:36**MOT test number** 490271236392**Result** ✓ Passed**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

**MOT #5** 2018-05-16 10:22**MOT test number** 811726070310**Result** ✗ Failed**Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Fail** Front Brakes imbalanced across an axle Axle 1 (3.7.B.5b)**Fail** Direction indicators adversely affected by the operation of another lamp (1.4.A.2h)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both (3.5.1i)**MOT #4** 2017-05-27 10:20**MOT test number** 747880808530**Result** ✓ Passed**MOT #3** 2016-06-29 14:37**MOT test number** 470924302261**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2015-06-03 14:48
MOT test number	208514755443
Result	✓ Passed
Notice	Engine management light illuminated during test
Notice	Under-trays fitted obscuring some underside components
Notice	Oil leak

MOT #1	2015-06-03 14:48
MOT test number	679304755190
Result	✗ Failed
Pass with rectification	Offside Front Direction indicator not working (1.4.A.2c)
Notice	Oil leak
Notice	Engine management light illuminated during test
Pass with rectification	Front Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Offside Front Headlamp not working on dipped beam (1.7.5a)
Notice	Under-trays fitted obscuring some underside components





Tax & MOT check

✕  
Untaxed

Tax expired:  
31 January 2024

✕  
MOT

Expired:  
25 October 2023

Tax status	Expired at 31 January 2024
Days left	89 days too late
MOT expiry date	25 October 2023
Full MOT history	<a href="#">See MOT history</a>



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>DU12DWM</b>
Plate since	2019-03-28
Current registration	<b>DU12DWM</b>
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-05-25
Last registration	2022-10-26
Complete history	<a href="#">See info</a>



Registration #1	2012-05-25	15 mi
Registration #2	2015-06-03	94.259 mi
Registration #3	2016-06-29	109.127 mi
Registration #4	2017-05-27	121.618 mi
Registration #5	2018-05-16	131.804 mi
Registration #6	2018-05-16	131.806 mi
Registration #7	2019-05-23	138.946 mi
Registration #8	2019-05-23	138.946 mi
Registration #9	2019-05-23	138.946 mi
Registration #10	2019-05-23	138.946 mi
Registration #11	2019-05-23	138.946 mi
Registration #12	2019-05-23	138.946 mi
Registration #13	2019-05-23	138.946 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2019 mm
Height	1721 mm
Length	3864 mm
Kerb weight	1321 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982998468