





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	E E 220 D SE
Colour	White
Year of manufacture	2017
Top speed	149 mph
0 - 100 km/h	7.3 seconds
0 - 60 mph	7.3 seconds
Gearbox	9 speed automatic

Engine & fuel consumption

Power	143 kW / 195 HP / 191 BHP
Max. torque	400 Nm at 1.600 rpm
Engine capacity	1.950 сс
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	В



CarCheck.co.uk page 1/10



report date: 2024-03-29


Internet history

Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT history

MOT expiry date	2022-04-05
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #3	2021-04-06 12:40
MOT test number	841500800114
Result	✓ Passed
Next expiry date	2022-04-05
Advice Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2		2020-09-18 08:46
MOT test	number	231563076195
Result		✓ Passed
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside front tyre tread cracking	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.4 (5.2.3 (e))	
Advice requires a	Front Brakes imbalanced requirements only just met. It would appear that the djustment or repair. $(1.2.1 (b) (i))$	braking system
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2.5 (5.2.3 (e))	

CarCheck.co.uk page 3/10



report date: 2024-03-29

MOT #1 2020-09-17 08:29

MOT test number 276547850961

Result ★ Failed

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system

requires adjustment or repair. (1.2.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2.4 (5.2.3 (e))

Advice Both front tyre treads cracking

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.5 (5.2.3 (e))

CarCheck.co.uk page 4/10




report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How man MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	NK SIX
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2017-09-27
Last registration	2021-04-06
Complete history	See info



Registration #1	2017-09-27	19 mi
Registration #2	2020-09-17	52.813 mi
Registration #3	2020-09-18	52.813 mi
Registration #4		11.777 es
Registration #5		11.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	86%
Children	77%
Pedestrian	59%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1852 mm
Height	1468 mm
Length	4923 mm
Wheel base	2939 mm
Kerb weight	1680 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack caluk	nago 10/1

CarCheck.co.uk page 10/10

Number of seats	5
Number of axles	2
Engine number	65492080163383