





report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Silver
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-12-14

Pictures 1

Listing price <u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-12
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #11		2024-01-09 09:57
MOT test	number	878080594232
Result		✓ Passed
Next expi	ry date	2025-01-12
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in exce	essive movement (5.3.4 (a)
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in e	excessive movement (5.3.4
Advice affecting of	Offside Rear Vehicle structure or chassis corroded within 30cm of a mounterest (6.2.2 (d) (i))	unting, but not seriously
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material	(1.1.11 (c))
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in ex	cessive movement (5.3.4
Advice (5.3.4 (a) (Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in	excessive movement
Advice affecting of	Nearside Rear Vehicle structure or chassis corroded within 30cm of a moverall security (6.2.2 (d) (i))	ounting, but not seriously

MOT #10		2022-12-29 11:36
MOT test	number	490416046554
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



KN13URZ

report date: 2024-03-29

 MOT #9
 2022-01-13 12:44

 MOT test number
 817603076727

 Result
 ✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

 MOT #8
 2021-03-17 15:47

 MOT test number
 427333147305

Result ✓ Passed

MOT #7 2020-03-04 13:58

MOT test number 884411109815

Result \rightarrow Passed

MOT #6 2020-03-03 15:00

MOT test number 442018087972

Result X Failed

Fail Hazard warning switch inoperative (4.4.2 (a) (ii))

MOT #5 2019-03-20 14:56

MOT test number 819895070991

MOT #4 2018-03-16 11:27

MOT test number 615583012438

Result ✓ Passed

Advice Items removed from driver's view prior to test

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Items removed from driver's view prior to test

Fail Nearside Rear Side repeater not working (1.4.A.2c)

Fail Nearside Rear Side repeater not working (1.4.A.2c)	
MOT #2	2017-03-27 10:39
MOT test number	202230656242
Result	✓ Passed
MOT #1	2016-03-23 09:37
MOT test number	803436905457
Result	✓ Passed
Advice Items removed from interior mirror	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	12 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-28
Last registration	2024-01-09
Complete history	See info



Registration #1	2013-03-28	23 mi
Registration #2	2016-03-23	29.359 mi
Registration #3	2017-03-27	35.413 mi
Registration #4	2018-03-15	40.383 mi
Registration #5	2018-03-16	40.383 mi
Registration #6	2019-03-20	45.279 mi
Registration #7	2020-03-03	48.813 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 46
Registration #13		10.000 au

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12