





report date: 2024-03-28

General information

Make	ТОУОТА
Model	HILUX ACTIVE 4X4 D-4D S/C
Colour	White
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	142 BHP
Max. torque	343 Nm at 2.800 rpm
Engine capacity	2.494 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	42.8 mpg
Consumption combined	38.7 mpg
CO2 emission	193 g/km
CO2 label	J



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-07-27

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2022-10-19
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	3
Total items failed	13

MOT #8	2021-10-20 15:53
MOT test number	266633442930
Result	✓ Passed
Next expiry date	2022-10-19
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #7	2021-10-14 08:41
MOT test number	634588439028
Result	X Failed
Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Steering column universal joint has excessive wear or play (2.2.2 (c))	
Fail Offside Front Service brake excessively binding (1.2.1 (f))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Fail Rear Prop shaft joint excessively worn (6.1.7 (c) (i))	
Fail Steering column universal joint insecure (2.1.3 (a) (i))	

CarCheck.co.uk page 3/12



Fail

FE15UHA

report date: 2024-03-28

MOT #6 2021-01-20 16:01 693111572885 **MOT** test number Result ✓ Passed **MOT #5** 2021-01-19 09:17 **MOT test number** 362138335431 Result × Failed Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #4

MOT test number

Fesult

Advice Emissions too clean to test

2020-01-13 14:28

531431054530

✓ Passed

Offside Parking brake inoperative on one side (1.4.1 (a))

 MOT #3
 2019-02-11 15:11

 MOT test number
 353400498415

 Result
 ✓ Passed

MOT #2

MOT test number

852907498411

Result

Fail Rear Prop shaft bearing excessively worn (6.1.7 (b) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2018-03-21 13:03

MOT test number 605448212684

CarCheck.co.uk page 5/12



Tax & MOT check

Tax expired: 8 July 2021



Expired: 19 October 2022 X MOT

Tax status	Expired at 8 July 2021
Days left	1026 days too late
MOT expiry date	19 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history

e mier metery	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
processor .	

manuse and the same and the sam	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	AIR AIR
Plate since	
Current registration	NK NK
Plate since	

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-23
Last registration	2021-10-20
Complete history	See info



Registration #1	2015-03-23	7 mi
Registration #2	2018-03-21	50.066 mi
Registration #3	2019-02-07	53.691 mi
Registration #4	2019-02-11	53.691 mi
Registration #5	2020-01-13	60.786 mi
Registration #6		T1.777 es
Registration #7		11.777 es
Registration #7 Registration #8		11.77 m
		11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
50295	
50482	
60501	
60566	
60567	
60569	

Dimensions & weight

Width	1760 mm
Height	1795 mm
Length	5260 mm
Kerb weight	1910 kg
Max. allowed weight	2730 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	2KDA684869

CarCheck.co.uk page 12/12