



**AX63BPE**

report date: 2024-03-28

General information

Make	MINI
Model	COOPER SD
Colour	Orange
Year of manufacture	2014
Top speed	134 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C







## Internet history

### Entry 3




Date	2022-12-10
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

### Entry 2

Date	2022-11-23
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

### Entry 1

Date	2021-02-02
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-12-13
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	17
Total items failed	5

MOT #12	2023-11-18 11:01
MOT test number	658826021224
Result	✓ Passed
Next expiry date	2024-12-13
Advice	Offside Rear Tyre slightly damaged tread worn unevenly (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11	2022-12-14 11:21
MOT test number	821195226248
Result	✓ Passed

MOT #10	2022-12-12 16:23
MOT test number	184805157151
Result	✗ Failed
Fail	Rear Outer Brake disc in such a condition that it is seriously weakened both (1.1.14 (a) (ii))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #9	2022-02-18 09:17
MOT test number	528947889774
Result	✓ Passed

**MOT #8** 2021-03-01 16:49**MOT test number** 772593605354**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2020-08-19 09:50**MOT test number** 407080086605**Result** ✓ Passed**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #6** 2019-09-23 13:46**MOT test number** 655626414403**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #5** 2019-09-23 11:01**MOT test number** 948406463262**Result** ✗ Failed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #4** 2018-09-21 10:01**MOT test number** 839176420132**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #3** 2017-08-25 09:37**MOT test number** 533063062028**Result** ✓ Passed**MOT #2** 2017-08-14 10:15**MOT test number** 364435109403**Result** ✗ Failed

**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #1** 2016-09-19 14:05**MOT test number** 158319364107**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
13 December 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	13 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-01-31
Last registration	2023-11-18
Complete history	<a href="#">See info</a>



Registration #1	2014-01-31	21 mi
Registration #2	2016-09-19	34.771 mi
Registration #3	2017-08-14	43.564 mi
Registration #4	2017-08-25	43.909 mi
Registration #5	2018-09-21	53.848 mi
Registration #6	2019-09-23	57.658 mi
Registration #7	2019-09-23	57.658 mi
Registration #8	2020-08-19	64.325 mi
Registration #9	2020-08-19	64.325 mi
Registration #10	2020-08-19	64.325 mi
Registration #11	2020-08-19	64.325 mi
Registration #12	2020-08-19	64.325 mi
Registration #13	2020-08-19	64.325 mi
Registration #14	2020-08-19	64.325 mi
Registration #15	2020-08-19	64.325 mi
Registration #16	2020-08-19	64.325 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1384 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1175 kg
Max. allowed weight	1465 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2

Number of axles	2
Engine number	91158896