



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI BLUEEFFICIENCY SPORT
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	250 Nm at 2.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-10-24
Pictures	0
Listing price	View report

source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-23
Pictures	22
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT #10	2022-12-31 09:58
MOT test number	707266921451
Result	✓ Passed
Next expiry date	2023-12-30
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9	2021-12-02 09:11
MOT test number	941013433019
Result	✓ Passed

MOT #8	2021-10-07 10:09
MOT test number	115072776930
Result	✗ Failed
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
MAJOR	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7	2020-10-29 19:15
MOT test number	165291361310
Result	✓ Passed

MOT #6	2020-10-29 19:15
MOT test number	221238987097
Result	✗ Failed
Pass with rectification	Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #5** 2019-04-05 14:06**MOT test number** 402072338474**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge out of shape/urgent (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge urgent (5.2.3 (e))**MOT #4** 2018-04-27 08:14**MOT test number** 276574416918**Result** ✓ Passed**MOT #3** 2017-04-28 15:08**MOT test number** 750524182695**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #2** 2017-04-28 09:20**MOT test number** 177679887914**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front tyre 0mm inner edge + deep cut in sidewall**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2016-04-13 08:46**MOT test number** 691835772666**Result** ✓ Passed**Advice** Under try restric from checking some of under vehicle componnents .



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 KS13UAW
Plate since	2019-03-29
Current registration	 KS13UAW
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-06-18
Last registration	2022-12-31
Complete history	See info



Registration #1	2013-06-18	24 mi
Registration #2	2016-04-13	18.577 mi
Registration #3	2017-04-28	25.318 mi
Registration #4	2017-04-28	25.318 mi
Registration #5	2018-04-27	34.108 mi
Registration #6	2019-04-05	40.565 mi
Registration #7	2020-10-29	47.467 mi
Registration #8	2022-12-31	47.467 mi
Registration #9	2022-12-31	47.467 mi
Registration #10	2022-12-31	47.467 mi
Registration #11	2022-12-31	47.467 mi
Registration #12	2022-12-31	47.467 mi
Registration #13	2022-12-31	47.467 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	81%
Pedestrian	56%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2010 mm
Height	1542 mm
Length	4359 mm
Wheel base	2699 mm
Kerb weight	1505 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	65190131839879