






report date: 2024-03-28

### General information

Make	FORD
Model	FUSION ZETEC
Colour	Blue
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	113 BHP
Max. torque	155 Nm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	157 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

### Internet history

#### Entry 1

Date 2021-07-30

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

# MOT history

MOT expiry date	2024-06-12
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	15
Total items failed	4

MOT #14	2023-06-13 14:26
MOT test number	879701879624
Result	✓ Passed
Next expiry date	2024-06-12
Advice Offside Front Wheel bearing slightly no	isy (5.1.3 (b) (i))
Advice Brake pedal wearing smooth (1.1.2 (c))	

MOT #13	2023-06-06 10:52
MOT test number	194838809819
Result	<b>X</b> Failed
Fail Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))	
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice Brake pedal wearing smooth (1.1.2 (c))	

MOT #12	2022-06-07 13:16
MOT test number	779989099047
Result	✓ Passed
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	

CarCheck.co.uk page 3/12



Result

**ML09TBY** 

report date: 2024-03-28

✓ Passed

MOT #11 2021-10-14 13:11

**MOT test number** 716750338800

**MOT #10** 2021-10-14 08:50

**MOT test number** 103005752306

Result X Failed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9 2021-02-12 09:49

**MOT test number** 921162394919

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #8 2019-04-23 12:56

**MOT test number** 321289123445

**Result** 
✓ Passed

**MOT #7** 2016-04-21 07:00

**MOT test number** 313201306045

**Result** ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6

MOT test number

919372335143

Result

Notice Child seat fitted not allowing full inspection of adult belt

MOT #5

MOT test number

266662935489

Result

Notice Child seat fitted not allowing full inspection of adult belt

Pass with rectification

Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

 MOT #4
 2014-05-07 15:07

 MOT test number
 528937224109

 Result
 ✓ Passed

 MOT #3
 2014-05-07 15:07

 MOT test number
 798427824140

 Result
 X Failed

 Pass with rectification
 Nearside Stop lamp not working (1.2.1b)

MOT #2

MOT test number

Result

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

 MOT #1
 2012-05-03 10:13

 MOT test number
 899794022194

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	12 June 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NA
Flate since	
Current registration	NK WIS
Plate since	
	More info

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-05-08
Last registration	2023-06-13
Complete history	See info



Registration #1	2009-05-08	8 mi
Registration #2	2012-05-03	17.038 mi
Registration #3	2013-05-03	20.765 mi
Registration #4	2014-05-07	25.065 mi
Registration #5	2015-05-12	31.149 mi
Registration #6	2016-04-21	34.176 mi
Registration #7	2019-04-23	34.669 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-28

# Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1839 mm
Height	1497 mm
Length	4337 mm
Kerb weight	1257 kg
Max. allowed weight	1825 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number Carcheck.co.uk	9G43569 page 12/12