



report date: 2024-03-28

General information

Make	KIA
Model	RIO CRDI CHILL
Colour	Silver
Year of manufacture	2008
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	235 Nm at 2.000 rpm
Engine capacity	1.493 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-06-11
Pictures	68
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-07-15
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	15
Total items failed	6

MOT #16	2022-07-16 10:55
MOT test number	390577985890
Result	✓ Passed
Next expiry date	2023-07-15
Advice	Brake fluid close to minimum mark (1.1.10 (d) (ii))

MOT #15	2022-07-16 10:55
MOT test number	341443649745
Result	✗ Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Brake fluid close to minimum mark (1.1.10 (d) (ii))

**MOT #14** 2022-07-15 15:50**MOT test number** 832866712173**Result** ✗ Failed

- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Nail in tyre
- Fail** Brake fluid contaminated (1.8 (a))

MOT #13 2021-06-17 11:23**MOT test number** 865545563593**Result** ✓ Passed**MOT #12** 2020-11-03 11:57**MOT test number** 565509269557**Result** ✓ Passed**MOT #11** 2019-11-07 17:31**MOT test number** 521683925711**Result** ✓ Passed

**MOT #10** 2019-11-07 13:03**MOT test number** 893663211564**Result** ✗ Failed**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Brake pipe excessively corroded front to rear pipes (1.1.11 (c))**MOT #9** 2018-11-12 12:51**MOT test number** 188430596202**Result** ✓ Passed**MOT #8** 2017-11-23 11:06**MOT test number** 851853932952**Result** ✓ Passed**MOT #7** 2017-11-23 11:06**MOT test number** 261524093976**Result** ✗ Failed**Pass with rectification** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**MOT #6** 2016-11-15 09:58**MOT test number** 537766775236**Result** ✓ Passed**MOT #5** 2015-11-10 12:48**MOT test number** 465434347310**Result** ✓ Passed

**MOT #4** 2014-11-24 10:43**MOT test number** 395058424376**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-11-13 10:29**MOT test number** 735677513318**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-11-13 11:26**MOT test number** 538448912396**Result** ✓ Passed**MOT #1** 2011-11-21 10:04**MOT test number** 207835821347**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✕
Untaxed

Tax expired:
1 December 2023

✕
MOT

Expired:
15 July 2023

Tax status	Expired at 1 December 2023
Days left	151 days too late
MOT expiry date	15 July 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	LS58RZL
Plate since	2019-09-29
Current registration	LS58RZL
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-11-27
Last registration	2022-07-16
Complete history	See info



Registration #1	2008-11-27	6 mi
Registration #2	2011-11-21	42.308 mi
Registration #3	2012-11-13	52.829 mi
Registration #4	2013-11-13	60.442 mi
Registration #5	2014-11-24	69.920 mi
Registration #6	2015-11-10	74.766 mi
Registration #7	2016-11-15	78.156 mi
Registration #8	2017-11-23	83.383 mi
Registration #9	2017-11-23	83.383 mi
Registration #10	2018-05-22	85.377 mi
Registration #11	2018-05-22	85.377 mi
Registration #12	2018-05-22	85.377 mi
Registration #13	2018-05-22	85.377 mi
Registration #14	2018-05-22	85.377 mi
Registration #15	2018-05-22	85.377 mi
Registration #16	2018-05-22	85.377 mi
Registration #17	2018-05-22	85.377 mi
Registration #18	2018-05-22	85.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1146 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FA8H366947