



General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	Silver
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-13
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #14</b>	2022-12-20 17:33
<b>MOT test number</b>	499814040362
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-12-30
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))
<b>Minor</b>	Front Windscreen wiper blade defective (3.4 (b) (i))
<b>Advice</b>	Rear Coil spring corroded both (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))

<b>MOT #13</b>	2022-12-20 17:33
<b>MOT test number</b>	447681487780
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))
<b>Pass with rectification</b>	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
<b>Pass with rectification</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>Advice</b>	Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Rear Coil spring corroded both (5.3.1 (b) (i))
<b>Minor</b>	Front Windscreen wiper blade defective (3.4 (b) (i))

<b>MOT #12</b>	2021-12-31 13:05
<b>MOT test number</b>	261139286983
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #11**

2021-12-30 16:14

**MOT test number**

824450783766

**Result****✗ Failed****DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #10**

2020-12-16 09:33

**MOT test number**

850818521033

**Result****✓ Passed****Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Drivers footwell carpet missing wiring exposed**MOT #9**

2019-06-19 11:24

**MOT test number**

379307334133

**Result****✓ Passed****Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2018-06-12 09:02**MOT test number** 229042642906**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2017-06-23 10:57**MOT test number** 109444266497**Result** ✓ Passed**MOT #6** 2017-06-23 10:57**MOT test number** 373381723375**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2016-06-23 09:22**MOT test number** 851130156042**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit close at 2.0mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit close at 3.0mm (4.1.E.1)**MOT #4** 2015-06-18 11:56**MOT test number** 278339765460**Result** ✓ Passed**MOT #3** 2014-06-24 14:11**MOT test number** 847455474132**Result** ✓ Passed



MOT #2	2013-05-09 09:36
MOT test number	568159323141
Result	✓ Passed

MOT #1	2013-04-23 12:44
MOT test number	445083413161
Result	✗ Failed
Fail	Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	N/s/r tyre worn down to 3mm, 2mm on inner and outer edges.
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-04
Last registration	2022-12-20
Complete history	<a href="#">See info</a>



Registration #1	2010-06-04	16 mi
Registration #2	2013-04-23	41.815 mi
Registration #3	2013-05-09	42.735 mi
Registration #4	2014-06-24	57.593 mi
Registration #5	2015-06-18	71.187 mi
Registration #6	2016-06-23	81.985 mi
Registration #7	2017-06-23	92.011 mi
Registration #8	2017-06-23	92.011 mi
Registration #9	2018-06-23	92.011 mi
Registration #10	2019-06-23	92.011 mi
Registration #11	2020-06-23	92.011 mi
Registration #12	2021-06-23	92.011 mi
Registration #13	2022-06-23	92.011 mi
Registration #14	2023-06-23	92.011 mi
Registration #15	2024-06-23	92.011 mi
Registration #16	2025-06-23	92.011 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

**Engine number**

AU21080