





report date: 2024-03-28

### General information

Make	FORD
Model	FUSION ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-28

### Internet history

### Entry 3

Date 2021-10-05

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 2

Date	2021-09-18

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-08-12
------	------------

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## MOT history

MOT expiry date	2024-08-12
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	20
Total items failed	10

MOT #16	2023-07-31 14:16
MOT test number	309141135814
Result	<b>✓</b> Passed
Next expiry date	2024-08-12

MOT #15	2023-07-31 09:57
MOT test number	626762079201
Result	<b>X</b> Failed
Advice Front Inner Brake disc worn, pitted or scored, but not seriously we (1.1.14 (a) (ii))  Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	eakened corroded& lipped

MOT #14		2022-08-05 16:09
MOT test	number	293125481180
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #13** 2022-08-05 11:24 **MOT** test number 168933965011 Result × Failed **Pass with rectification** Offside Headlamp aim too low (4.1.2 (a)) Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Fail** 

**MOT #12** 2021-07-26 09:18 130008389565 **MOT** test number Result Passed **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Nail in tyre

MOT #11		2020-08-11 11:06
MOT test	number	227689584423
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Nail in tyre	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge @ 3mm (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/13



report date: 2024-03-28

**MOT #10** 2020-08-11 11:06 506523552616 **MOT** test number Result × Failed **Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a)) Advice Offside Rear Tyre worn close to legal limit/worn on edge @ 3mm (5.2.3 (e)) **Advice** Nearside Rear Nail in tyre **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

 MOT #9
 2019-08-08 12:55

 MOT test number
 302271167924

 Result
 ✓ Passed

MOT test number

Result

Advice

Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

 MOT #7
 2017-08-09 09:38

 MOT test number
 877857852575

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #6		2017-08-09 09:38
MOT test number		736506328826
Result		<b>★</b> Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)	
Pass with rectification	Offside Stop lamp not working (1.2.1b)	

MOT #5		2016-08-11 08:27
MOT test number		129586748987
Result		✓ Passed
MOT #4		2016-08-11 08:27
MOT test number		933880760899
Result		<b>X</b> Failed
Pass with rectification	Offside Rear Direction indicators incorrect colour (1.4.A.2f)	
Pass with rectification	Nearside Rear Direction indicators incorrect colour (1.4.A.2f)	

MOT #3	2015-08-11 11:18
MOT test number	697403925276
Result	<b>✓</b> Passed
MOT #2	2014-08-11 15:27
MOT test number	515133924254
Result	<b>√</b> Passed
MOT #1	2013-08-13 15:28
MOT test number	765765023223
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	12 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	
*********	
***************************************	
**********	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK AR
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-06-03
Last registration	2023-07-31
Complete history	See info



Registration #1	2010-06-03	8 mi
Registration #2	2013-08-13	30.983 mi
Registration #3	2014-08-11	31.845 mi
Registration #4	2015-08-11	32.614 mi
Registration #5	2016-08-11	33.315 mi
Registration #6	2016-08-11	33.315 mi
Registration #7	2017-08-09	34.032 mi
Registration #8	2017-08-09	34.032 mi
Registration #9	2018-08-07	34.717 mi
Registration #10	2019-08-08	36.251 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es

More info >

CarCheck.co.uk page 12/13



GL10BHV report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1314 kg
Max. allowed weight	1835 kg

### Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1.

Number of axles 2

**Engine number** AP59922