



RENAULT

S060FGP

report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO LL DCI
Colour	White
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	16.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.900 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	53.3 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	42
Total items failed	9

MOT #19 2024-02-02 17:16

MOT test number 131637318917

Result ✓ Passed

Next expiry date 2025-02-01

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #18 2023-01-27 16:00

MOT test number 720882690181

Result ✓ Passed

Advice Brake pipe corroded, covered in grease or other material All brake pipes (1.1.11 (c))

MOT #17 2022-02-01 14:24

MOT test number 794194716576

Result ✓ Passed

**MOT #16** 2022-01-27 15:58**MOT test number** 212410688901**Result** ✗ Failed**MAJOR** Suspension arm pin or bush excessively worn osf (5.3.4 (a) (i))**MOT #15** 2021-09-13 07:35**MOT test number** 338988217713**Result** ✓ Passed**Advice** Offside Front Outer Drive shaft joint worn, but not excessively (6.1.7 (c) (i))**MOT #14** 2020-09-10 10:51**MOT test number** 981089880746**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**MOT #13** 2020-09-10 07:34**MOT test number** 906392092031**Result** ✗ Failed**MAJOR** Offside Rear Brake pipe excessively corroded to caliper (1.1.11 (c))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**MAJOR** Front Brake disc significantly and obviously worn both and pitted (1.1.14 (a) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Spare tyre defective**MAJOR** Offside Front Service brake lagging in operation (1.2.1 (d))**MAJOR** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

**MOT #12** 2019-09-19 13:24**MOT test number** 926460043152**Result** ✓ Passed**MOT #11** 2019-09-19 07:45**MOT test number** 449482858792**Result** ✗ Failed

- MAJOR** Offside Stop lamp(s) not working and high lever (4.3.1 (a) (ii))
- MAJOR** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Front Registration plate does not conform to the specified requirements (0.1 (d))
- MAJOR** Rear Direction indicator incorrect colour both (4.4.3 (a))
- MAJOR** Nearside Rear Brake pipe excessively corroded to caliper (1.1.11 (c))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #10 2018-09-17 12:03**MOT test number** 505882788874**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #9** 2018-09-17 12:03**MOT test number** 375739034483**Result** ✗ Failed**Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #8** 2017-09-14 13:59**MOT test number** 344509794144**Result** ✓ Passed**MOT #7** 2017-09-14 13:59**MOT test number** 733468997394**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Pass with rectification** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Pass with rectification** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

**MOT #6** 2016-09-12 19:11**MOT test number** 342292979539**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #5** 2016-09-12 19:11**MOT test number** 864378166223**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #4** 2015-08-20 17:57**MOT test number** 755814903691**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-08-27 19:29**MOT test number** 727109734288**Result** ✓ Passed**MOT #2** 2014-08-27 19:29**MOT test number** 378059934424**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #1** 2013-09-06 19:00**MOT test number** 548019643266**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 February
-------------------	------------------------

Days left	277
------------------	-----

MOT expiry date	1 February 2025
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-09-07
Last registration	2024-02-02
Complete history	See info



Registration #1	2010-09-07	17 mi
Registration #2	2013-09-06	21.455 mi
Registration #3	2014-08-27	27.801 mi
Registration #4	2015-08-20	34.925 mi
Registration #5	2016-09-12	42.682 mi
Registration #6	2016-09-12	42.682 mi
Registration #7	2017-09-14	50.102 mi
Registration #8	2017-09-14	50.102 mi
Registration #9	2018-09-17	57.261 mi
Registration #10	2018-09-17	57.261 mi
Registration #11	2019-09-17	64.420 mi
Registration #12	2019-09-17	64.420 mi
Registration #13	2020-09-17	71.579 mi
Registration #14	2020-09-17	71.579 mi
Registration #15	2021-09-17	78.738 mi
Registration #16	2021-09-17	78.738 mi
Registration #17	2022-09-17	85.897 mi
Registration #18	2022-09-17	85.897 mi
Registration #19	2023-09-17	93.056 mi
Registration #20	2024-02-02	93.056 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	D144474