





report date: 2024-03-29

# General information

Make	MAZDA
Model	6 SPORT NAV
Colour	Silver
Year of manufacture	2015
Top speed	121 mph
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	118 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2021-07-31

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT h	nistory
-------	---------

MOT expiry date	2024-07-05
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	14
Total items failed	4

MOT #8	2023-07-06 09:15
MOT test number	386391479523
Result	✓ Passed
Next expiry date	2024-07-05

MOT #7	2022-07-01 09:19
MOT test number	589969389145
Result	✓ Passed

MOT #6		2021-06-22 13:38
MOT test	number	129578293855
Result		✓ Passed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (	<b>(</b> ))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



Result

NG15EXF

report date: 2024-03-29

✓ Passed

**MOT #5** 2021-06-22 13:38 838057822605 **MOT** test number Result **X** Failed **Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4	2020-07-06 14:31
MOT test number	124800748734
Result	<b>✓</b> Passed
MOT #3	2019-08-23 15:56
MOT test number	617510163497
Result	<b>✓</b> Passed
MOT #2	2018-08-20 10:23
MOT test number	530363862488

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2018-08-17 12:22

**MOT test number** 397249280073

Result X Failed

Fail Offside Front Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 5/12



NG15EXF report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 July 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

## Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



NG15EXF report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
***************************************	
***************************************	
***************************************	
**********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	
Current registration	NIK NIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



NG15EXF report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



NG15EXF report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-08-18
Last registration	2023-07-06
Complete history	See info



Registration #1	2015-08-18	15 mi
Registration #2	2018-08-17	25.522 mi
Registration #3	2018-08-20	25.522 mi
Registration #4	2019-08-23	39.895 mi
Registration #5	2020-07-06	45.372 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea
•		1.77 m
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

# Safety ratings

NCAP rating	****
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1795 mm
Height	1465 mm
Length	4465 mm
Wheel base	2700 mm
Kerb weight	1205 kg
Max. allowed weight	1835 kg

# Additional information

Fuel tank capacity	51 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	PE 20561652

CarCheck.co.uk page 12/12