



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Yellow
Year of manufacture	2013
Top speed	113 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.3 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-01-05
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-29
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	15
Total items failed	15

MOT #14	2024-03-30 13:39
MOT test number	324019921379
Result	✓ Passed
Next expiry date	2025-03-29
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13	2024-03-28 15:09
MOT test number	815718719724
Result	✗ Failed
Fail	Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12** 2023-03-28 15:53**MOT test number** 541172529824**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2023-03-27 15:37**MOT test number** 578212683938**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))**Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))**MOT #10** 2022-03-30 14:07**MOT test number** 183171196515**Result** ✓ Passed

**MOT #9** 2022-03-14 16:50**MOT test number** 802431393959**Result** ✗ Failed**Fail** Halfshaft securing bolt missing diff bush (6.1.7 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #8** 2021-06-16 09:30**MOT test number** 812438954277**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2020-06-19 12:36**MOT test number** 299291318273**Result** ✓ Passed**MOT #6** 2020-06-16 10:06**MOT test number** 553190825684**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Registration plate lamp does not illuminate simultaneously with the position lamps both (4.7.2 (a))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))



MOT #5	2019-05-30 13:44
---------------	------------------

MOT test number	459710851149
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2018-05-18 16:01
---------------	------------------

MOT test number	898963579402
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2018-05-18 16:01
---------------	------------------

MOT test number	203339642174
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Rear Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	---

MOT #2	2017-05-15 16:24
---------------	------------------

MOT test number	139809709507
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2016-05-03 09:57
---------------	------------------

MOT test number	507068060039
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2024

✓

MOT

Expires:
29 March 2025

Tax status	Expired at 1 April 2024
Days left	27 days too late
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-06-10
Last registration	2024-03-30
Complete history	See info



Registration #1	2013-06-10	24 mi
Registration #2	2016-05-03	5.697 mi
Registration #3	2017-05-15	16.438 mi
Registration #4	2018-05-18	21.431 mi
Registration #5	2018-05-18	21.431 mi
Registration #6	2019-05-30	29.884 mi
Registration #7	2020-06-16	35.996 mi
Registration #8	2020-06-19	36.026 mi
Registration #9	2024-03-30	39,377 mi
Registration #10	2024-03-30	39,377 mi
Registration #11	2024-03-30	39,377 mi
Registration #12	2024-03-30	39,377 mi
Registration #13	2024-03-30	39,377 mi
Registration #14	2024-03-30	39,377 mi
Registration #15	2024-03-30	39,377 mi
Registration #16	2024-03-30	39,377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1936 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 286966K LNQ