




report date: 2024-12-04

General information

<b>Make</b>	MINI
<b>Model</b>	COUNTRYMAN COOPER S ALL4A COOPER S ALL4
<b>Colour</b>	White
<b>Year of manufacture</b>	-
<b>Top speed</b>	127 mph
<b>0 - 60 mph</b>	8.3 seconds
<b>Gearbox</b>	6 speed automatic

Engine & fuel consumption

<b>Power</b>	190 BHP
<b>Max. torque</b>	240 Nm at 1.600 rpm
<b>Cylinders</b>	4
<b>Fuel type</b>	Petrol
<b>Consumption city</b>	27.4 mpg
<b>Consumption extra urban</b>	45.6 mpg
<b>Consumption combined</b>	36.7 mpg





## Internet history



### Entry 2

Date	2022-11-14
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

### Entry 1

Date	2022-08-22
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



MOT history

<b>MOT #17</b>	2023-10-10 11:48
<b>MOT test number</b>	211684973300
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-10-09

<b>MOT #16</b>	2023-01-18 13:54
<b>MOT test number</b>	663938039568
<b>Result</b>	✓ Passed
<b>Advice</b>	Covers fitted masking testable items

<b>MOT #15</b>	2021-11-05 15:22
<b>MOT test number</b>	843184615291
<b>Result</b>	✓ Passed

<b>MOT #14</b>	2021-11-05 08:53
<b>MOT test number</b>	431238391743
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Fail</b>	Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

<b>MOT #13</b>	2020-11-13 10:31
<b>MOT test number</b>	431245881046
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre badly perished to tread
<b>Advice</b>	Rear subframe & underside corroded
<b>Advice</b>	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Nearside Steering rack gaiter slightly damaged
<b>Advice</b>	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))



<b>MOT #12</b>	2019-11-11 15:33
<b>MOT test number</b>	711797695075
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2019-11-11 10:56
<b>MOT test number</b>	979384705738
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
<b>Fail</b>	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
<b>Fail</b>	Service brake efficiency less than 50% of the required value (1.2.2 (a) (ii))

<b>MOT #10</b>	2018-11-19 15:54
<b>MOT test number</b>	179430272283
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
<b>Advice</b>	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
<b>Advice</b>	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))



**MOT #9** 2018-11-19 15:54

**MOT test number** 872468595282

**Result** ✗ Failed

- Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))

**MOT #8** 2017-10-25 11:45

**MOT test number** 878517066312

**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Various oil leaks

**MOT #7** 2016-10-20 08:18

**MOT test number** 116226447498

**Result** ✓ Passed

- Advice** Front brake disc worn
- Advice** Rear brake disc slightly worn
- Advice** Engine covers and under trays fitted



**MOT #6** 2016-10-20 08:18

**MOT test number** 416102905998

**Result** ✗ Failed

- Advice** Front brake disc worn
- Pass with rectification** Offside Front Headlamp aim too low (1.8)
- Advice** Rear brake disc slightly worn
- Pass with rectification** Nearside Front Headlamp aim too low (1.8)
- Advice** Engine covers and under trays fitted

**MOT #5** 2015-11-07 11:36

**MOT test number** 828044113236

**Result** ✓ Passed

- Advice** Rear tyres wearing on inside
- Advice** Front brake disc worn
- Advice** Front tyres wearing on inside
- Advice** Slight play in steering rack



MOT #4 2015-11-07 10:04

MOT test number 535133151458

Result ✗ Failed

- Advice Front brake disc worn
- Fail Nearside Front Headlamp aim too high (1.8)
- Fail Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice Front tyres wearing on inside
- Fail Parking brake: efficiency below requirements (3.7.C.1b)
- Advice Slight play in steering rack
- Fail Offside Front Headlamp aim too high (1.8)
- Fail Service brake: efficiency below requirements (3.7.C.1a)
- Advice Rear tyres wearing on inside

MOT #3 2014-11-12 12:53

MOT test number 918716714338

Result ✓ Passed

MOT #2 2013-12-10 14:14

MOT test number 929114643313

Result ✓ Passed

MOT #1 2013-12-09 09:59

MOT test number 776203143322

Result ✗ Failed

- Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





**Vehicle valuation**

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>WF60VUN</b>
Plate since	2019-09-29
Current registration	<b>WF60VUN</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-12-11
Last registration	2023-10-10
Complete history	<a href="#">See info</a>



Registration #1	2010-12-11	12 mi
Registration #2	2013-12-09	32.162 mi
Registration #3	2013-12-10	32.162 mi
Registration #4	2014-11-12	40.458 mi
Registration #5	2015-11-07	49.854 mi
Registration #6	2015-11-07	49.857 mi
Registration #7	2016-10-20	57.641 mi
Registration #8	2016-10-20	57.641 mi
Registration #9	2017-10-25	63.804 mi
Registration #10	2018-11-19	73.419 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi
Registration #17	2019-05-20	95.277 mi
Registration #18	2019-05-20	95.277 mi
Registration #19	2019-05-20	95.277 mi
Registration #20	2019-05-20	95.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1789 mm
Height	1577 mm
Length	4097 mm
Max. allowed weight	1865 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B7061855