



PEUGEOT

**S28NAF**

report date: 2024-03-28

General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	Grey
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-11
Pictures	2
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-20
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	44
Total items failed	3

MOT #16	2024-02-19 14:00
MOT test number	401830465711
Result	✓ Passed
Next expiry date	2025-02-20
Advice	Headlamp has a product on the lens but not seriously reducing light output front - nearside & offside (4.1.4 (b))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15**

2024-02-16 15:53

**MOT test number**

545829558063

**Result****✗ Failed**

- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Headlamp has a product on the lens but not seriously reducing light output front - nearside & offside (4.1.4 (b))
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))

**MOT #14**

2023-02-21 15:53

**MOT test number**

361494570119

**Result****✓ Passed**

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2023-02-20 15:15**MOT test number** 824473616236**Result** ✗ Failed**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Front Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Play in steering rack inner joint(s)**MOT #12** 2022-02-18 17:09**MOT test number** 148439832253**Result** ✓ Passed**MOT #11** 2021-08-20 13:09**MOT test number** 430938003884**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2021-08-18 08:08

**MOT test number**

375437089095

**Result****✗ Failed****MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Central Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9**

2020-09-04 13:48

**MOT test number**

296754239357

**Result****✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Nail in tyre**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Both front headlamps damaged but not insecure**Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**MOT #8**

2019-06-08 07:49

**MOT test number**

626043768862

**Result****✓ Passed**

**MOT #7** 2018-05-01 10:32**MOT test number** 107655359270**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-05-17 08:10**MOT test number** 561423637430**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-07-23 08:22**MOT test number** 470171527178**Result** ✓ Passed**MOT #4** 2016-07-22 12:45**MOT test number** 233681226692**Result** ✗ Failed**Fail** Front registration plate with character(s) which are not the correct width (6.3.4a)**Fail** Rear registration plate with character(s) which are not the correct width (6.3.4a)**MOT #3** 2015-07-18 11:38**MOT test number** 215449895465**Result** ✓ Passed**MOT #2** 2014-07-30 15:04**MOT test number** 607361014271**Result** ✓ Passed



MOT #1	2014-07-29 14:07
MOT test number	376920614404
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
20 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	20 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-07-30
Last registration	2024-02-19
Complete history	<a href="#">See info</a>



Registration #1	2011-07-30	28 mi
Registration #2	2014-07-29	30.730 mi
Registration #3	2014-07-30	30.774 mi
Registration #4	2015-07-18	38.447 mi
Registration #5	2016-07-22	45.696 mi
Registration #6	2016-07-23	45.709 mi
Registration #7	2017-05-17	48.646 mi
Registration #8	2018-05-01	49.462 mi
Registration #9	2019-06-08	55.614 mi
Registration #10	2020-06-08	55.614 mi
Registration #11	2020-06-08	55.614 mi
Registration #12	2020-06-08	55.614 mi
Registration #13	2020-06-08	55.614 mi
Registration #14	2020-06-08	55.614 mi
Registration #15	2020-06-08	55.614 mi
Registration #16	2020-06-08	55.614 mi
Registration #17	2020-06-08	55.614 mi
Registration #18	2020-06-08	55.614 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1350 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

