





report date: 2024-03-28

#### General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Grey
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

#### Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-28

### Internet history

		1
ᆮ	HLIV	-

Lifety 1	
Date	2021-10-05
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

#### MOT history

MOT expiry date	2024-10-19
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	25
Total items failed	5

MOT #13	2023-09-25 15:18
MOT test number	850613844322
Result	✓ Passed
Next expiry date	2024-10-19
Advice Rear Brake pipe corroded, covered in grease or other material n/s and o/s (1.1.11	(c))

MOT #12	2023-09-25 13:09
MOT test number	762390666463
Result	<b>X</b> Failed
Advice Rear Brake pipe corroded, covered in grease or other material n/s and o/  Minor Nearside Rear Registration plate lamp inoperative in the case of multiple (4.7.1 (b) (i))	, , , , ,
<b>Fail</b> Offside Front Outer Drive shaft joint constant velocity boot split or insecure, ingress of dirt (6.1.7 (g) (ii))	no longer prevents the

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #11** 2022-10-12 12:47 **MOT** test number 818183225893 Result ✓ Passed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e)) Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

960148096584

Result

Advice
Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice
(a) (i))

Advice
Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

2021-10-20 14:35 **MOT #9** 458875007295 **MOT** test number Result Failed Pass with rectification Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT test number

Result

Pass with rectification

Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #6

MOT test number

773215664207

Result

Advice Nearside Rear Nail in tyre

MOT #5

MOT test number

526421020950

Result

Advice Nearside Rear Nail in tyre

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4

MOT test number

845495782879

Result

✓ Passed

MOT #3

MOT test number 291055086941

Result × Failed

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))

MOT #2 2018-01-03 14:30 MOT test number 566792545184

Result \rightarrow Passed

MOT #1 2017-02-01 15:20

**MOT test number** 934208466473

Result \( \sqrt{Passed} \)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check





Expires: 19 October 2024

Tax status	Expired at 27 March 2024
Days left	34 days too late
MOT expiry date	19 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

^	1000
Owner	history
	IIISCOLV

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***************************************	
*******	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-04
Last registration	2023-09-25
Complete history	See info



Registration #1	2013-09-04	15 mi
Registration #2	2017-02-01	45.975 mi
Registration #3	2018-01-03	51.841 mi
Registration #4	2019-01-24	59.234 mi
Registration #5	2019-01-24	59.234 mi
Registration #6	2020-01-16	66.829 mi
Registration #7	2020-01-16	66.829 mi
Registration #8	2021-01-07	74.640 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11,117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



## Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

## Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13