



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO EASY
Colour	Grey
Year of manufacture	2014
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D





## MOT history

MOT expiry date	2025-04-21
MOT pass rate	53 %
MOT passed	8
Failed MOT tests	7
Total advice items	26
Total items failed	8

MOT #15	2024-04-22 14:10
MOT test number	507460904261
Result	✓ Passed
Next expiry date	2025-04-21
Minor	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #14	2024-04-22 14:10
MOT test number	619067727885
Result	✗ Failed
Minor	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Pass with rectification	Offside Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #13	2023-04-18 07:52
MOT test number	126225489847
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #12**

2023-04-17 14:18

**MOT test number**

502119762436

**Result****✗ Failed**

**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Pass with rectification** Offside Headlamp insecure (4.1.1 (c))

**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #11**

2023-04-17 11:01

**MOT test number**

448620780692

**Result****✗ Failed**

**Advice** Exhaust Rear Silencer Corroded

**MAJOR** Offside Front Headlamp insecure Retaining Brackets Broken (4.1.1 (c))

**DANGEROUS** Offside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure Sidewall Perished Exposing Cord (5.2.3 (d) (ii))

**Advice** Nearside Front Headlight Retaining Bracket Damaged

**Advice** Brake pipe corroded, covered in grease or other material Light Corrosion (1.1.11 (c))

**MOT #10**

2022-04-14 11:22

**MOT test number**

823632711005

**Result****✓ Passed**

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Perished and nail in tyre. (5.2.3 (d) (ii))

**Advice** Rear Rear exhaust box outer skin corroded.

**MOT #9** 2021-04-08 14:18**MOT test number** 215323741639**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))**MOT #8** 2021-04-06 12:22**MOT test number** 919017712346**Result** ✗ Failed**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords in tread (5.2.3 (d) (i))**MAJOR** Horn not working (7.7 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))**MOT #7** 2020-10-29 15:38**MOT test number** 276451254620**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre slightly damaged Wall (5.2.3 (d) (ii))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing Wall (5.2.3 (d) (ii))**MOT #6** 2020-10-29 15:38**MOT test number** 432692783288**Result** ✗ Failed**Advice** Nearside Rear Outer Tyre slightly damaged Wall (5.2.3 (d) (ii))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect Bulb fitted incorrectly (4.1.2 (c))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing Wall (5.2.3 (d) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid Both sides (3.5 (a))

**MOT #5** 2019-04-30 13:55**MOT test number** 648591339066**Result** ✓ Passed**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #4** 2019-04-30 13:55**MOT test number** 976567035752**Result** ✗ Failed**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #3** 2018-04-30 08:47**MOT test number** 604174170767**Result** ✓ Passed**Advice** Front cracking to tyres**MOT #2** 2018-04-30 08:47**MOT test number** 435843375871**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front cracking to tyres**MOT #1** 2017-04-12 08:55**MOT test number** 325375452396**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
21 April 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	21 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-04-30
Last registration	2024-04-22
Complete history	<a href="#">See info</a>



Registration #1	2014-04-30	22 mi
Registration #2	2017-04-12	16.594 mi
Registration #3	2018-04-30	23.916 mi
Registration #4	2018-04-30	23.916 mi
Registration #5	2019-04-30	29.248 mi
Registration #6	2019-04-30	29.248 mi
Registration #7	2020-10-29	36.978 mi
Registration #8	2020-10-29	36.978 mi
Registration #9	2020-10-29	36.978 mi
Registration #10	2020-10-29	36.978 mi
Registration #11	2020-10-29	36.978 mi
Registration #12	2020-10-29	36.978 mi
Registration #13	2020-10-29	36.978 mi
Registration #14	2020-10-29	36.978 mi
Registration #15	2020-10-29	36.978 mi
Registration #16	2020-10-29	36.978 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	0798077