




General information

Make	NISSAN
Model	350 Z V6
Colour	Grey
Year of manufacture	2009
Top speed	155 mph
0 - 60 mph	5.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	296 BHP
Max. torque	358 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.9 mpg
Consumption extra urban	31.7 mpg
Consumption combined	24.1 mpg
CO2 emission	280 g/km
CO2 label	M





Internet history

Entry 3

Date	2023-03-13
Pictures	10
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2


Date	2023-03-12
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2022-03-17
Pictures	10
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-10-05
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	7
Total items failed	11

MOT #16	2023-10-04 12:07
MOT test number	842485172454
Result	✓ Passed
Next expiry date	2024-10-05

MOT #15	2023-10-04 06:45
MOT test number	627362195520
Result	✗ Failed
Fail	Central Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
Fail	Nearside Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Offside Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))

MOT #14	2022-10-06 09:47
MOT test number	217008241320
Result	✓ Passed
Minor	Front Window damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #13	2021-10-22 10:53
----------------	------------------

MOT test number	840280543233
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
---------------	---

Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
---------------	--

MOT #12	2020-11-06 13:10
----------------	------------------

MOT test number	910997988659
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #11	2019-11-01 15:22
----------------	------------------

MOT test number	590429214411
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2018-10-26 14:25
----------------	------------------

MOT test number	207000686926
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2017-11-03 15:24
---------------	------------------

MOT test number	597139002563
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2016-11-04 12:26
---------------	------------------

MOT test number	215451657114
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #7** 2015-10-23 14:23**MOT test number** 843907956326**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-10-22 10:24**MOT test number** 326555894458**Result** ✓ Passed**MOT #5** 2013-10-25 11:41**MOT test number** 708818293286**Result** ✓ Passed**MOT #4** 2012-11-22 16:33**MOT test number** 589517822366**Result** ✓ Passed**MOT #3** 2012-11-22 16:33**MOT test number** 325837822354**Result** ✗ Failed**Pass with rectification** Nearside Front Direction indicator not working (1.4.A.2c)**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)**MOT #2** 2012-01-18 14:09**MOT test number** 397038312037**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #12012-01-18 14:09

MOT test number966178112089

Result		✗ Failed
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Pass with rectification	Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-01-21
Last registration	2023-10-04
Complete history	See info



Registration #1	2009-01-21	10 mi
Registration #2	2012-01-18	22.368 mi
Registration #3	2012-11-22	28.795 mi
Registration #4	2013-10-25	34.363 mi
Registration #5	2014-10-22	39.430 mi
Registration #6	2015-10-23	43.667 mi
Registration #7	2016-11-04	47.696 mi
Registration #8	2017-11-03	49.071 mi
Registration #9	2018-10-26	51.595 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi
Registration #15	2019-05-29	55.277 mi
Registration #16	2019-05-29	55.277 mi
Registration #17	2019-05-29	55.277 mi
Registration #18	2019-05-29	55.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1325 mm
Length	4315 mm
Wheel base	2650 mm
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	VQ35-607799