



report date: 2024-03-29

General information

Make	FIAT
Model	500C POP
Colour	Pink
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





## Internet history


## Entry 3

Date	2021-09-22
Pictures	19
Listing price	<a href="#">View report</a>

source: [cargurus.co.uk](https://www.cargurus.co.uk)


## Entry 2

Date	2021-09-20
Pictures	19
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](https://www.autotrader.co.uk)

## Entry 1

Date	2021-07-15
Pictures	5
Listing price	<a href="#">View report</a>

source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT expiry date	2024-08-05
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	18
Total items failed	6

MOT #15	2023-08-04 09:30
MOT test number	582792777961
Result	✓ Passed
Next expiry date	2024-08-05

MOT #14	2022-07-18 12:15
MOT test number	902811476554
Result	✓ Passed
Advice	Nearside Oil leak, but not excessive drive shaft oil seal (8.4.1 (a) (i))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #13	2021-08-06 11:12
MOT test number	407524778206
Result	✓ Passed

MOT #12	2021-08-05 13:53
MOT test number	311540055857
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #11** 2020-07-21 15:12**MOT test number** 156815640327**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Exhaust back box corroded**MOT #10** 2019-05-23 12:45**MOT test number** 106457065783**Result** ✓ Passed**MOT #9** 2019-05-23 11:07**MOT test number** 322751670823**Result** ✗ Failed**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #8** 2018-05-08 12:51**MOT test number** 158590829230**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear handbrake cable outer casing split**Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2017-05-10 13:53**MOT test number** 246709616571**Result** ✓ Passed**MOT #6** 2016-04-29 15:24**MOT test number** 172366171781**Result** ✓ Passed**MOT #5** 2016-04-29 10:55**MOT test number** 982213473351**Result** ✗ Failed**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**MOT #4** 2015-05-08 16:02**MOT test number** 456178525182**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Offside front door handle broken but still allowing access to the vehicle**MOT #3** 2015-05-07 17:05**MOT test number** 659587725154**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Offside front door handle broken but still allowing access to the vehicle**Fail** Offside Rear rear brake binding (3.7.B.1)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #2	2014-04-25 10:34
MOT test number	215675614119
Result	✓ Passed
Notice	Rear exhaust outer casing corroded
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2013-04-12 10:14
MOT test number	917902103163
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
5 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	5 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-04-19
Last registration	2023-08-04
Complete history	<a href="#">See info</a>



Registration #1	2010-04-19	15 mi
Registration #2	2013-04-12	23.984 mi
Registration #3	2014-04-25	31.989 mi
Registration #4	2015-05-07	38.877 mi
Registration #5	2015-05-08	38.877 mi
Registration #6	2016-04-29	40.849 mi
Registration #7	2016-04-29	40.849 mi
Registration #8	2017-05-10	42.365 mi
Registration #9	2018-05-08	4.358 mi
Registration #10	2019-05-23	45.708 mi
Registration #11	2019-05-23	45.708 mi
Registration #12	2019-05-23	45.708 mi
Registration #13	2019-05-23	45.708 mi
Registration #14	2019-05-23	45.708 mi
Registration #15	2019-05-23	45.708 mi
Registration #16	2019-05-23	45.708 mi
Registration #17	2019-05-23	45.708 mi
Registration #18	2019-05-23	45.708 mi
Registration #19	2019-05-23	45.708 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5582676