





report date: 2024-03-29

General information

Make	AUDI
Model	A3 TDI SPORT
Colour	Black
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg



CarCheck.co.uk page 1/11



MOT history

MOT #14	2020-11-14 11:47
MOT test number	279799323621
Result	✓ Passed
Next expiry date	2021-11-13
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #13	2020-11-14 11:47	
MOT test number	142544912415	
Result	★ Failed	
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt		
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #12		2019-10-26 12:21
MOT test	number	754423976588
Result		✓ Passed
Advice	Front Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #11	2018-08-16 16:14
MOT test number	102014553980
Result	✓ Passed

MOT #10		2016-11-15 16:00
MOT test	number	635034793251
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8	.3.1d)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3	3.1a)

CarCheck.co.uk page 2/11



MOT #9

MOT test number

732570087263

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2015-11-26 12:19 **MOT** test number 272142651631 Result **X** Failed Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Nearside rear brake binding (3.7.B.1) Fail Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #7		2014-11-24 09:34
MOT test	number	459558624471
Result		✓ Passed
Notice	Osr tyre worn	
Notice	Rear brake pads wearing thin	

CarCheck.co.uk page 3/11



MOT #6 2013-11-20 09:43

MOT test number 277504723368

Result Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Under-trays fitted obscuring some underside components

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Notice Items removed from driver's view prior to test

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Notice Osf tyre has damage to outer sidewall

MOT #5 2012-11-23 09:19

MOT test number 749838522307

Result ✓ Passed

MOT #4 2012-11-23 09:19

MOT test number 976998622341

Result X Failed

Pass with rectification Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

MOT #3 2011-11-21 09:16

MOT test number 399715521310

Result
✓ Passed

CarCheck.co.uk page 4/11



MOT #2 2011-11-21 09:16

MOT test number 216685521365

Result X Failed

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

MOT #1 2010-11-29 10:17

MOT test number 172143330303

Result

Passed

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners die Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2007-10-25
Last registration	2020-11-14
Complete history	See info



Registration #1	2007-10-25	24 mi
Registration #2	2010-11-29	26.527 mi
Registration #3	2011-11-21	35.384 mi
Registration #4	2012-11-23	39.290 mi
Registration #5	2013-11-20	49.712 mi
Registration #6	2014-11-24	60.950 mi
Registration #7	2015-11-26	71.784 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		0.77 66

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4203 mm
Wheel base	2578 mm
Kerb weight	1295 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	55 l	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number BXE 665529