



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	VERSO D-4D TR
Colour	Blue
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-28
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-08
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	50
Total items failed	9

MOT #18 2023-08-07 15:18**MOT test number** 971202970274**Result** ✓ Passed**Next expiry date** 2024-08-08

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view stonechip (3.2 (a) (i))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #17 2022-08-09 14:56**MOT test number** 776332151393**Result** ✓ Passed

- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sills both (5.3.6 (a) (i))

**MOT #16** 2022-08-09 14:56**MOT test number** 968341147029**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sills both (5.3.6 (a) (i))**MOT #15** 2021-08-06 10:03**MOT test number** 181107088002**Result** ✓ Passed**MOT #14** 2020-07-11 08:41**MOT test number** 600479788827**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13** 2020-07-10 10:21**MOT test number** 587807069631**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #12**

2019-07-12 17:03

MOT test number

583819073079

Result

✓ Passed

- Advice** Offside Rear nail in tyre
- Advice** Both rear indicator bulbs pale
- Advice** Tracking - tyre wear

MOT #11

2019-07-12 12:10

MOT test number

286147159432

Result

✗ Failed

- Advice** Both rear indicator bulbs pale
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Tracking - tyre wear
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear nail in tyre
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10

2018-07-13 09:46

MOT test number

597985222298

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2018-07-13 09:46**MOT test number** 316002666141**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #8** 2017-06-06 13:54**MOT test number** 568193492083**Result** ✓ Passed**MOT #7** 2017-06-06 10:36**MOT test number** 884421942615**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2016-06-07 12:38**MOT test number** 537785539721**Result** ✓ Passed**Advice** Rear discs pitted**Advice** Offside Rear tyre perished



MOT #5	2015-06-08 11:51
MOT test number	255639455426
Result	✓ Passed
Notice	OS wiper slightly smears
Notice	Rear discs slightly pitted
Notice	Under-trays fitted obscuring some underside components
Notice	Rear tyres perished

MOT #4	2014-06-06 09:59
MOT test number	197077354177
Result	✓ Passed

MOT #3	2013-06-06 09:35
MOT test number	997567153138
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Notice	Edge wear off side front tyre
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Off side front near side rear tyres perished



MOT #2

2013-06-06 09:35

MOT test number

456657653142

Result

✗ Failed

Pass with rectification

Offside Rear position lamp(s) not working (1.1.A.3b)

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Notice

Edge wear off side front tyre

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Notice

Off side front near side rear tyres perished

MOT #1

2012-06-08 15:30

MOT test number

415050262157

Result

✓ Passed

Notice

Front brake imbalance high just within spec

Notice

Surface corrosion on all brake discs



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
8 August 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-06-01
Last registration	2023-08-07
Complete history	See info



Registration #1	2009-06-01	25 mi
Registration #2	2012-06-08	38.412 mi
Registration #3	2013-06-06	55.863 mi
Registration #4	2014-06-06	71.907 mi
Registration #5	2015-06-08	87.264 mi
Registration #6	2016-06-07	100.978 mi
Registration #7	2017-06-06	112.608 mi
Registration #8	2017-06-06	112.608 mi
Registration #9	2018-07-13	125.254 mi
Registration #10	2018-07-13	125.254 mi
Registration #11	2019-06-01	138.968 mi
Registration #12	2019-06-01	138.968 mi
Registration #13	2019-06-01	138.968 mi
Registration #14	2019-06-01	138.968 mi
Registration #15	2019-06-01	138.968 mi
Registration #16	2019-06-01	138.968 mi
Registration #17	2019-06-01	138.968 mi
Registration #18	2019-06-01	138.968 mi
Registration #19	2019-06-01	138.968 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1625 kg
Max. allowed weight	2260 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	1AF5454242
---------------	------------