





General information

| Make | MAZDA |
|---------------------|----------------|
| Model | MX-5 SPORT NAV |
| Colour | Silver |
| Year of manufacture | 2016 |
| Top speed | 133 mph |
| 0 - 60 mph | 7.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 158 BHP |
|-------------------------|---------------------|
| Max. torque | 200 Nm at 4.600 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 30.4 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 40.9 mpg |
| CO2 emission | 161 g/km |
| CO2 label | G |







Internet history

| Entry 1 | |
|----------|--|
| Date | |
| Pictures | |


2021-07-04

21

Listing price

View report









source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-07-06 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 3 |

| MOT #7 | 2023-06-26 15:24 |
|------------------|------------------|
| MOT test number | 430231682922 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-06 |

| MOT #6 | 2022-07-07 09:30 |
|-----------------|------------------|
| MOT test number | 444421770362 |
| Result | ✓ Passed |

| MOT #5 | 2021-06-25 08:57 |
|-----------------|------------------|
| MOT test number | 620846176741 |
| Result | ✓ Passed |
| | |

Advice Nearside Front Tyre worn close to legal limit/worn on edge tread at 2-3mm. worn bold inner and outer edges (5.2.3 (e))

| MOT #4 | | 2020-10-06 12:02 |
|----------|--|------------------|
| MOT test | number | 269981971260 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |





| MOT #3 | 2020-10-05 14:58 |
|--|----------------------------------|
| MOT test number | 206909483836 |
| Result | ✓ Passed |
| Advice Offside Front Inner Tyre slightly damaged/crackin | g or perishing (5.2.3 (d) (ii)) |
| Advice Offside Front Nail in tyre | |
| Advice Nearside Front Inner Tyre slightly damaged/crack | ng or perishing (5.2.3 (d) (ii)) |
| Minor Windscreen damaged but not adversely affecting of | river's view (3.2 (a) (i)) |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| | Μ | ΟΤ | #2 |
|--|---|----|----|
|--|---|----|----|

Result

2019-09-11 16:24

205003112590

MOT test number

✓ Passed

| MOT #1 | 2019-09-11 15:36 |
|---|------------------|
| MOT test number | 199244661781 |
| Result | 🗙 Failed |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |



Tax & MOT check

| Tax due: 1 August 2024 | ✓ Taxed | Expires: 6 July 2024 | ✓ МОТ |
|----------------------------------|------------|--------------------------------|----------------------|
| Tax status | | | Valid until 1 August |
| Days left | | | 95 |
| MOT expiry date | | | 6 July 2024 |
| Full MOT history | | | See MOT history |
| Tax calculation | | | |

| Vehicle class | 48 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | |
| Category | 4. ARANPE |
| Туре | |
| Damage 2 | AMPL |
| Damage 2 | E CUT-S |
| Date | 14 N |
| Category | AMP |
| Туре | |

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second s | |
|--|-------------|
| ********** | |
| ******** | |
| NUMBER OF TAXABLE PARTY | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2016-09-03 |
| Last registration | 2023-06-26 |
| Complete history | See info |



| Registration #1 | 2016-09-03 | 11 mi |
|-----------------|------------|------------|
| Registration #2 | 2019-09-11 | 59.675 mi |
| Registration #3 | 2019-09-11 | 59.675 mi |
| Registration #4 | 2020-10-05 | 87.664 mi |
| Registration #5 | 2020-10-06 | 87.717 mi |
| Registration #6 | | 11.117 esi |
| Registration #7 | | 11.117 esi |
| Registration #8 | | 11.117 esi |
| Registration #9 | | 11.777 esi |

More info >





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 80% |
| Pedestrian | 93% |
| Safety systems | 64% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|--|--------------------------|
| Width | 1735 mm |
| Height | 1230 mm |
| Length | 3915 mm |
| Wheel base | 2310 mm |
| Kerb weight | 1000 kg |
| Max. allowed weight | 1260 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 45 I |
| | 45 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 2 |