





report date: 2024-03-29

General information

Make	BMW
Model	330 330D XDRIVE M SPORT TOURING
Colour	Silver
Year of manufacture	2017
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	56.5 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-25
Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/11



YB17FDE report date: 2024-03-29

MOT history

MOT expiry date	2025-02-20
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	9
Total items failed	0

MOT #9	2024-02-21 15:44
MOT test number	369364014167
Result	✓ Passed
Next expiry date	2025-02-20

MOT #8	2023-06-29 16:16
MOT test number	653136842514
Result	√ Passed

MOT #7	2023-06-29 13:57
MOT test number	667850915731
Result	X Failed

DANGEROUS Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #6		2022-06-27 12:03
MOT test	number	550510578527
Result		✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Brake disc worn, pitted or scored, but not seriously weakened inner surface on both front brake discs slightly pitted (1.1.14 (a) (ii))		

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5 2022-06-27 10:29

MOT test number 100247975469

Result X Failed

MAJOR Nearside Side repeater not working (4.4.1 (a) (ii))

Advice Brake disc worn, pitted or scored, but not seriously weakened inner surface on both front brake discs slightly pitted (1.1.14 (a) (ii))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #4 2021-07-05 14:18

MOT test number 834154737169

Result
✓ Passed

MOT #3 2020-12-09 15:51

MOT test number 225980609696

Result ✓ Passed

MOT #2 2020-12-08 13:00

MOT test number 113567240650

Result ★ Failed

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2.4mm (5.2.3 (e))

MOT #1 2020-06-22 05:10

MOT test number 154155289185

Result
✓ Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	20 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



YB17FDE report date: 2024-03-29

Owner history

Owner history		
For how long did the current and previous owner(s) have this BMW? How many owners did Check it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ve?

THE STREET STREE		

	More info	>
Plate changes Coo in this check if this RMW had different purpher plates		
See in this check if this BMW had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-06-30
Last registration	2024-02-21
Complete history	See info



Registration #1	2017-06-30	22 mi
Registration #2	2020-12-08	34.461 mi
Registration #3	2020-12-09	34.662 mi
Registration #4		11.777 es
Registration #5	2021-07-05	38.001 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 es
		11.777 ea 11.777 ea
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1429 mm
Length	4633 mm
Wheel base	2810 mm
Kerb weight	1680 kg
Max. allowed weight	2225 kg

Additional information

Fuel tank capacity	57 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11

Number of axles 2

Engine number 73279973