



report date: 2024-03-29

General information

Make	VOLVO
Model	S90 D5 POWERPULSE R-DESIGN AWD
Colour	Grey
Year of manufacture	2017
Top speed	145 mph
0 - 60 mph	6.7 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	235 BHP
Max. torque	480 Nm at 2.250 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history




Entry 3

Date	2023-12-05
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 2

Date	2021-08-12
Pictures	28
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2021-07-31
Pictures	8
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-05
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #5	2023-11-06 12:28
MOT test number	782753059275
Result	✓ Passed
Next expiry date	2024-11-05
Advice	Front Brake pad(s) wearing thin around 4mm left (1.1.13 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4	2022-11-04 12:13
MOT test number	736994067476
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3	2021-11-02 15:25
MOT test number	945434188318
Result	✓ Passed



MOT #2	2021-11-02 15:25
MOT test number	676634226114
Result	✗ Failed
Pass with rectification	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #1	2020-09-23 14:30
MOT test number	431354097695
Result	✓ Passed
Advice	Tyre worn close to legal limit/worn on edge NSF tyre heavy wear at inner shoulder and slight edge wear at OSF inner shoulder. (5.2.3 (e))
Advice	Tyre slightly damaged/cracking or perishing All tyres slight perishing at shoulders. (5.2.3 (d) (ii))



Tax & MOT check

X

Untaxed

Tax expired:
2 April 2024

✓

MOT

Expires:
5 November 2024

Tax status	Expired at 2 April 2024
Days left	27 days too late
MOT expiry date	5 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-25
Last registration	2023-11-06
Complete history	See info



Registration #1	2017-09-25	29 mi
Registration #2	2020-09-23	30.319 mi
Registration #3	2019-09-23	30.319 mi
Registration #4	2019-09-23	30.319 mi
Registration #5	2021-11-02	37.302 mi
Registration #6	2019-09-23	30.319 mi
Registration #7	2019-09-23	30.319 mi
Registration #8	2019-09-23	30.319 mi
Registration #9	2019-09-23	30.319 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	2019 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1763 kg
Max. allowed weight	2360 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	2049020
---------------	---------