



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 HDI SR
Colour	Grey
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-10
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-21
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	24
Total items failed	6

MOT #152023-08-22 13:41

MOT test number952887975657

Result✓ Passed

Next expiry date2024-08-21

- Advice**Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice**Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice**Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))
- Minor**Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice**Front Headlamp has a product on the lens but not seriously reducing light output Both sides (4.1.4 (b))
- Advice**Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

**MOT #14**

2023-08-22 09:16

MOT test number

449409261087

Result**✗ Failed****Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output Both sides (4.1.4 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))**MAJOR** Nearside Front Tyre fouling a part of the vehicle Wheel liner as marked (5.2.3 (f))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #13**

2022-08-10 13:16

MOT test number

833859340678

Result**✓ Passed****MOT #12**

2022-08-09 14:43

MOT test number

549018600838

Result**✗ Failed****MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #11** 2021-08-04 11:01**MOT test number** 699025782590**Result** ✓ Passed**MOT #10** 2020-07-13 11:32**MOT test number** 263413478893**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2019-07-29 10:12**MOT test number** 930072416909**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #8** 2018-08-13 12:25**MOT test number** 967758716442**Result** ✓ Passed**MOT #7** 2018-01-02 11:14**MOT test number** 300391414795**Result** ✓ Passed**MOT #6** 2016-12-16 08:52**MOT test number** 925216207646**Result** ✓ Passed

**MOT #5** 2016-12-15 14:34**MOT test number** 708169693696**Result** ✗ Failed**Fail** Exhaust system not adequately supported (7.1.1)**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #4** 2016-03-15 12:51**MOT test number** 138845178489**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all around (3.5.1i)**Advice** Centre exhaust bracket broken**MOT #3** 2016-03-15 12:51**MOT test number** 746601879660**Result** ✗ Failed**Advice** Centre exhaust bracket broken**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Brake disc worn, pitted or scored, but not seriously weakened all around (3.5.1i)**MOT #2** 2015-03-24 10:48**MOT test number** 499173185001**Result** ✓ Passed**MOT #1** 2014-03-25 13:32**MOT test number** 817864184041**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
21 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	21 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-04-30
Last registration	2023-08-22
Complete history	See info



Registration #1	2011-04-30	27 mi
Registration #2	2014-03-25	44.571 mi
Registration #3	2015-03-24	49.097 mi
Registration #4	2016-03-15	52.024 mi
Registration #5	2016-03-15	52.024 mi
Registration #6	2016-12-15	58.471 mi
Registration #7	2016-12-16	58.471 mi
Registration #8	2018-01-02	59.434 mi
Registration #9	2018-08-13	60.213 mi
Registration #10	2019-05-22	61.277 mi
Registration #11	2019-05-22	61.277 mi
Registration #12	2019-05-22	61.277 mi
Registration #13	2019-05-22	61.277 mi
Registration #14	2019-05-22	61.277 mi
Registration #15	2019-05-22	61.277 mi
Registration #16	2019-05-22	61.277 mi
Registration #17	2019-05-22	61.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	87%
Pedestrian	41%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4792 mm
Wheel base	2817 mm
Max. allowed weight	1975 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2

