





report date: 2024-03-28

#### General information

Make	MINI
Model	MINI COOPER S
Colour	White
Year of manufacture	2013
Top speed	141 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	190 BHP
Max. torque	260 Nm at 1.700 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



### Internet history

_	_	_		_	-
드	n	C	ľν	7	1

Lifety 1	
Date	2021-07-24
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



# MOT history

MOT expiry date	2024-10-31
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #10	2023-11-01 11:05
MOT test number	263106189963
Result	✓ Passed
Next expiry date	2024-10-31
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g)	(i))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9		2022-10-28 10:16
MOT test	number	523858421701
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #8 2022-10-28 10:16

**MOT test number** 648487234015

Result X Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2021-09-13 08:12

**MOT test number** 757585075173

**Result** 
✓ Passed

MOT #6 2021-03-02 13:42

**MOT test number** 334490828553

**Result** ✓ Passed

MOT #5 2020-03-18 13:37

**MOT test number** 582928288710

**Result** ✓ Passed

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #4 2019-03-19 09:11

MOT test number 656941409039

**Result** ✓ Passed

**MOT #3** 2018-03-20 10:40

MOT test number 675017807380

CarCheck.co.uk page 4/12



MOT #2	2017-03-27 15:22
MOT test number	914973368516
Result	<b>✓</b> Passed
MOT #1	2016-06-16 10:38
MOT #1 MOT test number	2016-06-16 10:38 448927244325

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	31 October 2024
Full MOT history	See MOT history

#### Tax calculation

William .	40
Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



#### Owner history

e union matery	
For how long did the current and previous owner(s) have this MINI? How many owners die Check it in the premium report and see all owner registrations. Download the full report is	
********	
********	
*************	
Plate changes	More info >
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-06-06
Last registration	2023-11-01
Complete history	See info



Registration #1	2013-06-06	15 mi
Registration #2	2016-06-16	21.603 mi
Registration #3	2017-03-27	24.154 mi
Registration #4	2018-03-20	31.411 mi
Registration #5	2019-03-19	36.789 mi
Registration #6	2020-03-18	42.058 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1892 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 12/