





report date: 2024-03-29

General information

Make	TOYOTA
Model	PRIUS VVT-I T4
Colour	Grey
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed CVT

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-05

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-12-08
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	19
Total items failed	6

MOT #15	2023-12-04 13:09
MOT test number	335084132063
Result	✓ Passed
Next expiry date	2024-12-08
Advice Rear Exhaust has a minor leak of exha	aust gases (6.1.2 (a))
Advice Rear under seal corroded	

MOT #14	2023-12-0	04 13:09
MOT test number	642520	0151211
Result		X Failed
Pass with rectification minimum depth required is	Nearside Front Tyre tread pattern not visible over the whole tread area w 1.0mm (5.2.3 (e))	hen
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Rear Exhaust ha	s a minor leak of exhaust gases (6.1.2 (a))	
Advice Rear under seal	corroded	
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Advice (b))

Advice (b))

Advice (b))

Advice (b)

Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #12

MOT test number

671208788056

Result

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11 2021-11-17 14:50 **MOT** test number 968146252591 Result × Failed **Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) **Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) **Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Fail Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

 MOT #10
 2020-12-09 10:50

 MOT test number
 278925955923

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #9

MOT test number

878692670265

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2019-02-25 14:12 **MOT** test number 835052046779 Result ✓ Passed **MOT #7** 2018-02-08 14:26 **MOT** test number 177035377471 ✓ Passed Result MOT #6 2017-02-25 09:40 995693769683 **MOT** test number

Result

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

 MOT #5
 2016-02-20 10:46

 MOT test number
 914251043766

 Result
 ✓ Passed

MOT #4 2015-02-25 15:48

MOT test number 126176655050

Result Passed

Notice Both rear tyres starting to perish and crack

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3		2014-02-26 12:22
MOT test	number	625527854080
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2012-11-01 11:01
MOT test number	299046202376
Result	✓ Passed
MOT #1	2011-10-27 12:06
MOT test number	678300201395
Result	√ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	8 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	В
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

_	
Owner	hictory
OWITE	HIISLUH V

e when mistery	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-11-06
Last registration	2023-12-04
Complete history	See info



Registration #1	2008-11-06	29 mi
Registration #2	2011-10-27	12.491 mi
Registration #3	2012-11-01	17.278 mi
Registration #4	2014-02-26	21.305 mi
Registration #5	2015-02-25	31.810 mi
Registration #6	2016-02-20	38.075 mi
Registration #7	2017-02-25	43.797 mi
Registration #8	2018-02-08	50.620 mi
Registration #9	2019-02-25	56.583 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1325 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1.

Number of axles 2

Engine number 1NZ5248639