





report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER
Colour	Silver
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	168 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



Internet history

	-	٠	B43.4	,	1
_	ш	L	ΙV		ж,

Elitiy 1	
Date	2021-09-15
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



✓ Passed

MOT history

Result

MOT expiry date	2024-09-29
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	12
Total items failed	2
MOT #10	2023-09-12 15:17
MOT test number	949418454567
Result	✓ Passed
Next expiry date	2024-09-29
MOT #9	2022-09-29 15:54
MOT test number	547906383128
Result	✓ Passed
MOT #8	2021-09-30 13:33
MOT test number	613849532241

MOT #7	2020-11-20 09:14
MOT test number	155297077308

MOT #6	2020-02-06 14:58
MOT test number	664269345887
Result	✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Engine covers and under trays obscuring some components

CarCheck.co.uk page 3/12



MOT #5

EF13OJR report date: 2024-03-28

2019-01-30 17:16

MOT test number 364896348832

MOT #4 2018-05-21 12:38

MOT test number 859382553907

Result
✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #3 2018-05-19 10:29

MOT test number 397572365182

Result X Failed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Nearside Rear Sidewall of tyre age cracked.

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2 2017-06-22 10:43

MOT test number 682665095193

Result \(\sqrt{Passed} \)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front brake pads wearing thin

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear tyre has some cracks/splits in the tread (no cord showing)

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/12



MOT #1 2016-06-03 11:22

MOT test number 648348012251

Result ✓ Passed

Advice

Offside Lower Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra MINI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report is	

Plate changes	More info >
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	AIS UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-06-28
Last registration	2023-09-12
Complete history	See info



Registration #1	2013-06-28	28 mi
Registration #2	2016-06-03	15.245 mi
Registration #3	2017-06-22	20.780 mi
Registration #4	2018-05-19	24.556 mi
Registration #5	2018-05-21	24.556 mi
Registration #6	2019-01-30	24.872 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11 .117 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1295 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number A708J575