





report date: 2024-03-29

## General information

Make	MERCEDES-BENZ
Model	CLA CLA180 AMG SPORT
Colour	Black
Year of manufacture	2015
Top speed	130 mph
0 - 100 km/h	9.2 seconds
0 - 60 mph	9.2 seconds
Gearbox	7 speed automatic

## Engine & fuel consumption

Power	90 kW / 123 HP / 122 BHP
Max. torque	200 Nm at 1.250 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	122 g/km
CO2 label	D



CarCheck.co.uk page 1/11



## Internet history

## Entry 1

Date 2021-08-03

Pictures 32

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-09
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	20
Total items failed	3

MOT #8	2023-10-10 16:31
MOT test number	898226754818
Result	✓ Passed
Next expiry date	2024-10-09
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Minor Windscreen wiper blade defective (3.4 (b) (i))	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Vehicle under covers not allowing full inspection on some components	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/11



LC15VKG

report date: 2024-03-29

**MOT #7** 2023-10-10 16:31 **MOT** test number 313820584679 Result × Failed Minor Windscreen wiper blade defective (3.4 (b) (i)) **Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Oil leak, but not excessive (8.4.1 (a) (i)) Advice Advice Vehicle under covers not allowing full inspection on some components Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #6

MOT test number

268468017309

Result

Advice

Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #5

MOT test number

343855387574

Result

✓ Passed

MOT #4

MOT test number

Result

Pass with rectification

Nearside Headlamp aim too low (4.1.2 (a))

Pass with rectification

Offside Headlamp aim too low (4.1.2 (a))

CarCheck.co.uk page 4/11



MOT #3 2020-07-08 13:53

MOT test number 219000867784

**Result** ✓ Passed

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Nearside Front Seat belt buckle slightly damaged (7.1.2 (d))

**MOT #2** 2019-06-22 11:09

**MOT test number** 402228700878

Result \sqrt{Passed}

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #1** 2018-06-21 16:51

**MOT test number** 625125320701

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MERCEDES-BENZ salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	
********	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-06-26
Last registration	2023-10-10
Complete history	See info



Registration #1	2015-06-26	8 mi
Registration #2	2018-06-21	35.657 mi
Registration #3	2019-06-22	42.772 mi
Registration #4	2020-07-08	46.884 mi
Registration #5	2021-07-29	51.425 mi
Registration #6		m.m-
Registration #6 Registration #7		11,777 ea
-		11,777 ea 11,777 ea
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



## Dimensions & weight

Width	2032 mm
Height	1432 mm
Length	4630 mm
Wheel base	2699 mm
Kerb weight	1330 kg
Max. allowed weight	1920 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack co.uk	nago 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	27091030728822