



Mercedes-Benz

**DUIIAAE**

report date: 2024-03-29

General information

Make	MERCEDES
Model	A-CLASS A180 CDI AVANTGARDE SE
Colour	Blue
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	11.1 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	144 g/km
CO2 label	F





MOT history

MOT expiry date	2025-01-27
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	14
Total items failed	9

MOT #15	2024-01-21 14:44
MOT test number	822776834993
Result	✓ Passed
Next expiry date	2025-01-27
Advice	Under tray and engine covers fitted
Advice	Rear Brake pad(s) wearing thin n/s & o/s (1.1.13 (a) (ii))

MOT #14	2023-01-18 16:16
MOT test number	805875853645
Result	✓ Passed
Advice	Under tray and engine covers fitted

MOT #13	2022-01-28 16:37
MOT test number	901503102746
Result	✓ Passed

**MOT #12**

2022-01-21 16:29

**MOT test number**

630826443899

**Result****✗ Failed****Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**MOT #11**

2022-01-06 11:05

**MOT test number**

222699953940

**Result****✗ Failed****Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Central Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Rear Tyre slightly damaged/cracking or perishing on both sides also worn on the inner ( 185/55/16 ) (5.2.3 (d) (ii))**Fail** Emissions not tested due to exhaust leak (8.2.2.2 (e))**MOT #10**

2021-01-20 15:47

**MOT test number**

135791920179

**Result****✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #9** 2021-01-20 09:17**MOT test number** 231363918910**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm also cut (5.2.3 (e))**MOT #8** 2020-02-17 19:09**MOT test number** 268449733114**Result** ✓ Passed**MOT #7** 2020-02-15 17:16**MOT test number** 907150129341**Result** ✗ Failed**Fail** Fuel system component leaking under bonnet at diesel filter (6.1.3 (b) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Pass with rectification** Offside Front Lower Driver's door hinge insecure (6.2.3 (c) (ii))**MOT #6** 2019-02-26 15:54**MOT test number** 412722128144**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #5** 2018-02-26 14:46**MOT test number** 172510986047**Result** ✓ Passed



MOT #4 2017-02-22 10:25

MOT test number 549607328842

Result ✓ Passed

MOT #3 2016-02-10 10:52

MOT test number 406344290271

Result ✓ Passed

MOT #2 2015-02-10 11:09

MOT test number 345751545092

Result ✓ Passed

MOT #1 2014-02-14 10:51

MOT test number 196215544485

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
27 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	27 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	<b>DU11AAE</b>
Plate since	2019-03-29
Current registration	<b>DU11AAE</b>
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-01
Last registration	2024-01-21
Complete history	<a href="#">See info</a>



Registration #1	2011-03-01	7 mi
Registration #2	2014-02-14	12.544 mi
Registration #3	2015-02-10	14.720 mi
Registration #4	2016-02-10	17.755 mi
Registration #5	2017-02-22	26.411 mi
Registration #6	2018-02-26	39.095 mi
Registration #7	2019-02-26	54.500 mi
Registration #8	2020-02-15	73.287 mi
Registration #9	2020-05-20	85.377 mi
Registration #10	2020-05-20	95.377 mi
Registration #11	2020-05-20	105.377 mi
Registration #12	2020-05-20	115.377 mi
Registration #13	2020-05-20	125.377 mi
Registration #14	2020-05-20	135.377 mi
Registration #15	2020-05-20	145.377 mi
Registration #16	2020-05-20	155.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1764 mm
Height	1593 mm
Length	3838 mm
Wheel base	2568 mm
Kerb weight	1380 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094030788625