



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T3
Colour	Grey
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-17
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #18</b>	2023-04-28 11:16
<b>MOT test number</b>	878619993019
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-04-27
<b>Advice</b>	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
<b>Advice</b>	Nearside wing mirror repaired with tape
<b>Advice</b>	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

<b>MOT #17</b>	2022-03-09 15:48
<b>MOT test number</b>	329794294995
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
<b>Advice</b>	Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #16</b>	2022-03-09 15:48
<b>MOT test number</b>	213688516523
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Pass with rectification</b>	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

<b>MOT #15</b>	2021-01-28 16:12
<b>MOT test number</b>	141506192014
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Child Seat fitted not allowing full inspection of adult belt x2

**MOT #14**

2021-01-26 14:37

**MOT test number**

408397934373

**Result**

✗ Failed

**Fail** Nearside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt x2**Fail** Nearside Rear Tyre has ply or cords damaged outer wall (5.2.3 (d) (ii))**Fail** Offside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**MOT #13**

2020-01-14 11:46

**MOT test number**

471282000059

**Result**

✓ Passed

**Advice** Rear under side corroded**Advice** N/s rear tyre outer wall scuffed**Advice** N/s rear arch damaged**Advice** N/s and o/s rear radius arm front bushes deterated**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #12**

2019-01-14 14:39

**MOT test number**

834809300177

**Result**

✓ Passed

**Advice** N/s and o/s rear radius arm front bushes deterated**Advice** Rear under side corroded**Advice** N/s rear tyre outer wall scuffed**Advice** N/s rear arch damaged**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #11**

2018-01-15 10:08

**MOT test number**

888258796056

**Result**

✓ Passed

**Advice** Nearside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive arch (2.4.A.3)

**Advice** Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)

**Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)

**Advice** Rear under body slight corrosion

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)

**MOT #10**

2017-01-12 14:00

**MOT test number**

293827926662

**Result**

✓ Passed

**Advice** Nearside Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Rear suspension corroded

**Advice** Body has slight corrosion under body (6.1.B.2)

**Advice** Offside Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Upper Body has slight corrosion (6.1.B.2)

**MOT #9**

2016-01-21 11:29

**MOT test number**

473863792768

**Result**

✓ Passed

- Advice** Child seat fitted
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Slight play in n/s front top sus/mount
- Advice** Under trays and engine covers fitted
- Advice** Rear tyres wearing on edges
- Advice** Under side and suspension slight corrosio
- Advice** Exhaust brackets rusty

**MOT #8**

2016-01-18 14:53

**MOT test number**

947930009586

**Result**

✗ Failed

- Advice** Rear tyres wearing on edges
- Advice** Exhaust brackets rusty
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Under side and suspension slight corrosio
- Advice** Slight play in n/s front top sus/mount
- Advice** Under trays and engine covers fitted
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Child seat fitted

**MOT #7**

2015-01-21 14:01

**MOT test number**

546441525068

**Result**

✓ Passed

- Advice** Body has slight corrosion (6.1.B.2)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (2.4.G.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (2.4.G.1)

**MOT #6**

2014-01-13 09:53

**MOT test number**

809133314044

**Result**

✓ Passed

- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Advice** Rear Body has slight corrosion (6.1.B.2)
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5**

2013-01-14 12:44

**MOT test number**

396964113057

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2011-11-29 15:26**MOT test number** 476313731315**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2010-12-16 09:39**MOT test number** 250630350349**Result** ✓ Passed**Notice** Offside front wiper blade split but still clears screen**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-12-15 14:55**MOT test number** 523079440318**Result** ✗ Failed**Fail** Nearside Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside front wiper blade split but still clears screen**Fail** Nearside Front Front wheel bearing rough when rotated (2.5.A.2)**MOT #1** 2010-01-21 14:18**MOT test number** 431061620050**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>RA56CSU</b>
Plate since	2019-03-29
Current registration	<b>RA56CSU</b>
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-01-24
Last registration	2023-04-28
Complete history	<a href="#">See info</a>



Registration #1	2007-01-24	7 mi
Registration #2	2010-01-21	23.407 mi
Registration #3	2010-12-15	29.151 mi
Registration #4	2010-12-16	29.151 mi
Registration #5	2011-11-29	36.067 mi
Registration #6	2013-01-14	45.114 mi
Registration #7	2014-01-13	51.461 mi
Registration #8	2015-01-21	59.127 mi
Registration #9	2016-01-18	65.144 mi
Registration #10	2016-01-21	65.169 mi
Registration #11	2016-01-21	65.169 mi
Registration #12	2016-01-21	65.169 mi
Registration #13	2016-01-21	65.169 mi
Registration #14	2016-01-21	65.169 mi
Registration #15	2016-01-21	65.169 mi
Registration #16	2016-01-21	65.169 mi
Registration #17	2016-01-21	65.169 mi
Registration #18	2016-01-21	65.169 mi
Registration #19	2016-01-21	65.169 mi
Registration #20	2016-01-21	65.169 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	2AD521824