





### General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Red
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А







### Internet history

Entry 1

Date Pictures 2021-02-19

12

Listing price

View report



source: yesauto.com



### MOT history

MOT expiry date	2025-03-07
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	5
Total items failed	4

MOT #11	2024-02-23 10:12
MOT test number	630671874398
Result	✓ Passed
Next expiry date	2025-03-07

MOT #10	2024-02-17 10:50
MOT test number	380265151850
Result	🗙 Failed
<b>Fail</b> Offside Front Tyre has a tear, caused by separation or partial failure of its	s structure (5.2.3 (d) (ii))

МОТ #9	2023-03-04 15:57
MOT test number	353286278945
Result	✓ Passed

МОТ #8	2023-03-04 14:46
MOT test number	702924523963
Result	🗙 Failed
<b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Rear Tyre has ply or cords exposed outer side walls (5.2.3 (d) (ii))	





MOT #7	2022-02-19 09:38
MOT test number	739030258188
Result	✓ Passed
МОТ #6	2021-03-05 15:34
MOT test number	374394067599
Result	✓ Passed

MOT #5	2020-03-02 16:02
MOT test number	698317913166
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #4	2020-03-02 13:19
MOT test number	684483013788
Result	🗙 Failed
<b>Fail</b> Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3		2019-03-05 15:53
MOT test	number	218867164737
Result		✓ Passed
Advice	Nearside Front Inner Road wheel slightly distorted bead (5.2.2 (c) (i))	
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	

MOT #2	2018-03-08 15:57
MOT test number	778023629639
Result	✓ Passed
Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	





MOT #1	2017-04-10 14:41
MOT test number	143069406887
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 March 2025	✓ MOT Expires: 7 March 2025
Tax status	Valid until 1 March
Days left	305
MOT expiry date	7 March 2025
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48

Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	 
Category	 AMPL
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
**********	
********	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-04-30
Last registration	2024-02-23
Complete history	See info



Registration #1	2014-04-30	11 mi
Registration #2	2017-04-10	3.564 mi
Registration #3	2018-03-08	12.256 mi
Registration #4	2019-03-05	19.134 mi
Registration #5	2020-03-02	29.989 mi
Registration #6	2020-03-02	29.989 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 esi





### Car features

S0225	Air conditioning
S0295	
S0482	
50501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight	
Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	905 kg
Max. allowed weight	1190 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	7552662