



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO GP
Colour	Blue
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 3

Date	2023-11-30
Pictures	22
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date	2021-10-30
Pictures	10
Listing price	View report



source: [yesauto.com](https://www.yesauto.com)

Entry 1

Date	2021-07-21
Pictures	11
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-11-29
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	18
Total items failed	9

MOT #15	2023-11-30 12:58
MOT test number	424111004476
Result	✓ Passed
Next expiry date	2024-11-29
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14	2023-11-30 12:58
MOT test number	551755965178
Result	✗ Failed
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2022-11-06 14:16**MOT test number** 744007142997**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Brake cable damaged but not to excess parking brake cable (1.1.15 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2021-11-15 14:43**MOT test number** 366488704332**Result** ✓ Passed**MOT #11** 2021-11-15 14:43**MOT test number** 672156720963**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #10** 2020-10-16 12:52**MOT test number** 181061189801**Result** ✓ Passed**Advice** Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))

**MOT #9** 2020-10-16 08:35**MOT test number** 131253936043**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))**MOT #8** 2019-10-19 08:22**MOT test number** 549417869713**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7** 2018-10-06 07:48**MOT test number** 594594581349**Result** ✓ Passed**MOT #6** 2017-10-02 08:17**MOT test number** 874879014338**Result** ✓ Passed**MOT #5** 2016-10-28 12:36**MOT test number** 729671769354**Result** ✓ Passed**MOT #4** 2015-09-08 13:57**MOT test number** 491051181370**Result** ✓ Passed

**MOT #3** 2015-09-08 08:37**MOT test number** 500992373064**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2015-06-05 14:13**MOT test number** 305436155187**Result** ✓ Passed**Notice** Rear exhaust corroded (not leaking at time of test)**Notice** Both rear tyres perishing (175/65 R15 85T)**Notice** Coolant stain on nearside cylinder head coolant jacket**MOT #1** 2014-06-05 11:44**MOT test number** 668916054148**Result** ✓ Passed**Notice** All four tyres outer sidewalls starting to perish 175.65.15h**Notice** Both front brake discs worn and corroded



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
29 November 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-06-29
Last registration	2023-11-30
Complete history	See info



Registration #1	2011-06-29	7 mi
Registration #2	2014-06-05	24.211 mi
Registration #3	2015-06-05	35.689 mi
Registration #4	2015-09-08	37.367 mi
Registration #5	2015-09-08	37.367 mi
Registration #6	2016-10-28	43.287 mi
Registration #7	2017-10-02	50.363 mi
Registration #8	2018-10-06	63.790 mi
Registration #9	2019-10-19	82.349 mi
Registration #10	2020-10-16	98.077 mi
Registration #11	2020-10-16	98.077 mi
Registration #12	2020-10-16	98.077 mi
Registration #13	2020-10-16	98.077 mi
Registration #14	2020-10-16	98.077 mi
Registration #15	2020-10-16	98.077 mi
Registration #16	2020-10-16	98.077 mi
Registration #17	2020-10-16	98.077 mi
Registration #18	2020-10-16	98.077 mi
Registration #19	2020-10-16	98.077 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6332630